MARLENE TOOGOOD

	LAND	CORNER F	RECORDATION CER	RTIFICATE	20U 19	티 91	ΡM	3 24	
	Filing i	Requireme	ent of Act 74, Mich.	P.A. 1970	37 01	IIA CT	111	U L I	
For corners in				1		e?	,	\supset	P.
Newaygo	Located In:		Corner Code ##	,	m	ىلەملىن	<u>'-</u> /	00 BOS-	7
(Catarity)	7 7 7 7	1 / Y Y							
 Public Land Survey 	<u> </u>		A-2		with.	001	19 60	N 2	
	T R _				VOL	OOT	TAUL		
	T R . T R .								
2. Property Controlling	S T R								
in Section	S T R								
3. Miscellaneous							itamp 8	File Nu	ımber
Property in Sec.	S R _		A 115 TE 1/1001						
4. Lot No , R	locarded Plat								JKLK
5. Private Claims	ecorded rear				A B	- 	E F G	- H I	
					² � − 6-		-4-	- 3 -	-2-1-
					3	+ +			
Norman T. Ooha		October	- 16 9'	3	4 - 7-	— ė.— 	9-+	-10	-1112
Norman L. Ochs do hereby certify that under req	, in a field survey on	igan P.A. of 19	370 the corner points me	entioned	1				
in lines 1 and 2 above were in	conformance with regula	ations and ru	les therefore as require	ed in the	- 18-	17	16-1	-15	-1413
current manual of survey instru	actions of the United State	es Departmer	nt of the Interior, Bureau	of Land	7				1
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					8 — 19	20-	21	-22	-2324
Court of Law; established, re	e-established, monument	ted, re-moni	umented, recovered, fo	ound as	9				
expressed below:					10 — 30	29-	28-1	-27	-2625
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					12 31				75 36
on this certificate. W. 1/4 Corner, Sec	tion 6 Bridgeto	m Than	Newaygo County	Mich.	13 31-	32	33		35-30
A. Description of original r	monument and accesso	ories and/or	subsequent restorati	on:	, , , , , , , , , , , , , , , , , , , ,				
	מ		h 11/7/50	197	72 M.S				
G.L.O. John Mullet 10" Y. Oak Corner	R R	LS #3421	<u>-</u>	1''	Pipe le Po	Flush	with	paveme	ent "o
10 1. Oak Willer		as Pipe		Tel	le. Po	Le Nb2	_e 4b	.94	150 119
N.C.R.C. Sheet	4	IZ" ELM S	570 ⁰¹ E 78.8' #. ak S20 ⁰¹ E 91.4	2 0°	Elm N Elm l	0/ E J	3.33		ĺÔ
Pina		or Fenc	e Post East 33		(No di		oive		
Spike in Maple S70°	E /0.U 7/4 ==	Pele. Pol	Le N40 ⁰ ±E 59.3'	₩5	XX.0 CI_	004.04	0-,-	,	
Spike in Tw. Cherry	S20°E 76.4 #3						(See o	ver)
B. Description of corner e	id-ass found and/or a	aathad ann	liad in restoring or res	etablishina etablishina	corner:				
A-2 1/4 Corner	Section 6 & 1	l on Co	unty Line, T	11N, R1	4W.				
Found 2" Harrison									v
Centerline of Blac	k top is 1 1/2 f	eet West	t, set by Lazaro	ock in go	ood co	nd.			
Condition of r	occaded withou	reac ic	# 1 thru 2	are go	ne.#	11 200	d con	ditio	a,
#12 gone, #13 gone.	#4 Good Condit			 5					<u>.</u>
- ·	34 / E = = =	,	_	o for the	i	mer	₩ ±b	that	in
I am aware that the mind I have searche	ere is not a pos	her conf	Hicting evidence	e that w	rould :	indica	te an	alte	mate
location. Finding	none I accept th	e Harris	on monument as	a carefu	ıl and	faith	ful r	e-esta	ablishme
of the position of	the original cor	ner.							
•	J								
				•					
C. Description of monume	at for porner and acces	corios asta	iblished to perpetuate	locating th	e nositio	n of the	corner:		
			ionsired to perpetuate	, .ooug					-
Newaygo Engineerin	ig and Survey Co.	•							
Found 2" Harrison	Cast Iron Monum	ment in 1	Monument Box a	nd accep	ted fo	r 1/4	corne	r, an	d is
accepted as a care	ful and faithful	l reestal	olishment of th	e positio	on of	the or	igiala	Tr GOT	nex.
40 PAIDLE 044 E 20	/./+ TCCC - DET/	OII DIV.	U JULIU			á	* V V /	*********	C. T.
SW. Leg of Tower a 1/2" Rod and Cap We	it ground NO3 E 2	1.S #3	:c. 0389 William Fr	ies īr l	-		المريد	IORMAN	
Power Pole \$89 W 6	37.90 feet - Nail	Lin Sout	th side			Ž	k f	L. OCHS	**************************************
TOMOT TOTO DON MA O	., , , , , , , , , , , , , , , , , , ,	=	·-· -			2 1	s S	LAND Urveyo	R
						3	6	22/139	
. 1	(0, 1	`				4	1	ELTIJI Programan	CIR TELET
1/2	L Carl	/_,	0-1-	Novem	ber 8,	1993	The	DIAND	A STATE OF THE STA

Norman L. Ochs Surveyor's Michigan License No. Approved by Peer Croup on December 21 Norman L. Ochs, County Representative

Signed by

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

November 8, 1993

A. cont.
Ralph A. Smith R.L.S. #3421
Field Book 56 Pg. 43
Gas Pipe
18" Maple S45°+E 90.0' #4
30" Elm S65°+E 77.2' #2
T.Pole N40°+E 59.3' #5
Fe. Post East 30.0' #6

John Lazarock #7867 9-28-83.
Set 3" County Suggested & Mon. Box Conc. R.O.W. Marker East 47.76' #12 36" Maple SE 90.80' #4
Conc. R.O.W. Marker West 51.77' #13 P.Pole West 69.22' #11
Recorded in Liber 1270, Page 870.

Recorded in Liber 1270, Page 870 P. Pole West 69.45' #11 48' Elm Stp. ESE 78.84' #2 T. Pole (moved) NNE 59.65' #5

Charles F. Lewandowski 6-10-82

Found 1" Bolt on top 1" Pipe in Mon. Box Surveyor legend in mon. box P.Pole West 69.13' #11 R.O.W. Marker East 47.75' #12 36" Maple S43°E 90.83' #4 Recorded in Liber 1240 Page 522.

On March 18, 1953 Raplh A. Smith R.L.S. #3421 measured 2668.2 feet from the SW. Corner to the W. 1/4 Corner. Michigan State Highway Department measured 2667.7 feet from the SW. Corner to the W. 1/4 Corner of Sec. 6 and 2669.3 feet from the W. 1/4 Corner to the NW. Corner of Sec. 6. In 1967 Patrick A. Salisbury R.L.S. #13594 measured 2667.38 feet from the Sw. Corner to the W. 1/4 Corner of Sec. 6 and 2669.02 feet from the W. 1/4 Corner to the NW. Corner of Sec. 6.