MAR 1 3 2000

1999 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDI IL DROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '00 FEB 28 PM 1 10

For corners in Newaygo (County)	Located in:	Corner Code #	Linda V	n. Brown
1. Public Land Survey	T <u>12N</u> R <u>14W</u> T <u>11N</u> R <u>14W</u> TR T R	G-13 G-1	" vol. 2	311
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & F	ile Number
points mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior. Burel Law and/or that the corner poconformance with the rules of Decree of a Court of Law, estab recovered, found as expressed by	, in a field survey on August irements of P. A. 74, Michigan P. above were in conformance with an unit manual of survey instructions at of Land Management or by ants mentioned in lines 3, 4 and the Michigan Board of Land ished, re-established, monumerelow:	A. of 1970, the corner regulations and rules of the United States a decree of a Court of ad 5 above were in Surveyors or by a nited, re-monumented,	A B C D E F H 2 - 6 - 5 - 4 - 3 3 - 7 - 8 - 9 - 10 5 - 18 - 17 - 16 - 15 7 - 19 - 20 - 21 - 22 9 - 10 - 30 - 29 - 28 - 27 11 - 30 - 29 - 28 - 27	- 2 - 1
Southwest Corner, Section 3 Northwest Corner, Section 3	4, Sheridan Township, News		12 31 + 32 + 33 + 34	35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 Sheridan Township 20" Hemlock N37°W 24 Links (15.84')#1 20" Hemlock N66°E 24 Links (15.84')#2

Bridgeton Township 12" Beech S45°E 16 Links (10.56')#3 10" Hemlock S32°W 18 Links (11.88')#4

William M. Jacques (County Surveyor) 1904 Filed with Register of Deeds Found no corner. Established by measurement from Northeast Corner of Section 2 West to the Northwest Corner of Section 4. New corner post made of pine root.

William Fries, Jr. #30389 LCRC #903 February 22, 1989 Set 1/2" Iron and cap 33 feet South of a fence to the East, North of an East and West trail, and in fence line occupation to the West and North 8" Cherry N22°E 29.12' #5 11" Maple N66°E 39.92' #6 9" Oak East 13.83' #7 10" Triple Cherry S26°W 44.36' #8

Donald G. Sandel R.L.S. #25870 February 23, 1999 Recorded in Liber 374, Page 1069 Found Fries capped iron 16" Poplar S81°E 13.67' #9 8" Poplar S42°E 36.34' #10 18" Cherry S31°W 44.35' #8 6" Poplar S81°W 37,75' #11

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" Rod and cap #30389 on old fence going North and the centerline of the East and West two-track is 14.5 feet ± South. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #11 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1/2" Rerod and cap #30389 and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

•		
12" Cherry N17°E 29.37' Set spike with tag #22439 In Sout 20" Maple N66°E 40.25' Set spike with tag #22439 In North 16" Red Oak East 14.28' Set spike with tag #22439 in East	nerly side of tree. #6	NORMAN
24" Triple Cherry S21°W 44.64' Set spike with tag #2249 ir	of tree #8	
16" Popular S81°E 13.67'#9	· · · · · · · · · · · · · · · · · · ·	S LE LAND :
8" Popular S42°E 36.34' #10		SURVEYOR Ho.
6" Popular S81°W 37.75' #11		22439
Signed by Mormon L. Ochs	Date	THO LAND SUP
Norman L. Ochs		- Allennia
Surveyor's Michigan License No. 22439	Form approved by Mi	chigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on October 28, 1999 Norman L. Ochs, County Representative.		Revised May 14, 1975 Revised Jan., 1983