SURVEY & REMONUMENTATION

APR 04 1996

1995 Newaygo County Remonumentation Project

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

h. P.A. 1970	NEWAYGU COUNTY REGION OF U. MARLE . EGGGGOD
	196 FEB 21 FM 9 37
vol. 1	PAGE 1610 good
Register of Deed	s_Stamp & File_Number
2 6-6-3	C D E F G H I J K L M

13

For corners in Located in: Corner Code # Newaygo (County) 1. Public Land Survey T <u>11N</u> R <u>14W</u> G-2 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

4. Lot No. _, Recorded Plat 5. Private Claims

Norman L. Ochs , in a field survey on September 23 19 95 do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

W. 1/4 Comer, Section 3, Bridgeton Twp., Newaygo Co., MI

10 11 12

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1837 8" Hemlock N49°W 4Lks (2.64')#1 10" Hemlock S70°E 7Lks (4.62')#2

William M. Jacques (Co. Surveyor) Book B Pg's 2 & 3 and Book 14 Pg's 49 & 50 November 15, 1904 Stone corner-original corner Measured 36.05 ch (2379.30 ft) from the N.W. Cor. to the W. 1/4 Cor. of Sec. 3 and measured 40.22 ch (2654.52 ft) from the W. 1/4 Cor. to the S.W. Cor. of Sec. 3

NCRC Sheet (1930's thru 1950's) 1½" Iron pipe N.W. Cor. hse. S45°E 90.5' #3 15" Pine S20°E 87.0' #4

Newaygo Engineering and Survey Co. February 26, 1980 Found 11/4" Pipe 2"-10" Clump Maple N40±°W 31.89' #5 N.W. Cor. hse. S45±°E 93.91' #3 24" W. Pine S25±°E 86.68' #4

William Fries Jr. RLS #30389 In 1986 found bent pipe 2' deep and repaced with 1/2" Iron and cap LCRC #1135 June 28, 1991 N.E. Cor. garage S25°E 81.83' #6 Multi Maple trunk N30°W 31.81' #5 4" Cherry N10°E 38.95' #7 North face center sign post S45°E 47.90' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½"rod and cap by William Fries, Jr. P.S. #30389 and found crockery a foot deep and measured 5199.43 ft from the W.¼ Cor. to the E. ¼ Cor. of Sec. 3. The centerline of the East and West road is 2 ft South and on centerline of road South and the condition of the recorded witnesses are: #1 thru #3 gone, #4 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ½" rod and cap and set a 4" dia. Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner. OF BICHIGA

28" Pine S20°E 87.60' #4
2"-10" Clump Maple N40°W 31.82' #5
N.E. Corner garage S25°E 81,80' #6
4" Cherry N10°E 38.96' #7
North face center sign post S45°E 47.84' #8
N.E. Corner House S55°W 118.14'

Date __ October 2, 1995

FO LAND Norman L. Ochs Surveyor's Michigan License No. Form approved by Michigan State Board of Land Surveyor

Revised May 14, 1975 Revised Jan., 1983

NORMAN L. OCHS SURVEYOR 22439

Approved by Peer Review Group On December 13, 1995 Norman L. Ochs, County Representative M.L. O.