	EAIND CORNER	T RECORDATION CENTIFICATE	,	OD4	- 0)O	
For corners in	Filing Require	ment of Act 74, Mich. P.A. 1970	NOT.	001 PA	ibe C	90	
		ı				•	
Newaygo (County)	Located In:	Corner Code ##					
Public Land Survey	T 12N R 12W	<u> </u>	REG	WAYGO C ISTER OF RLENE TO	DEÊ	D'S	
	T R	* +	MAN	ILCHE IV	10600	. U	
Property Controlling in Section	T R S T R S T R			98 14 P		_	
3. Miscellaneous	S T R	Re	gister of Dec	eds Stemp 3	E File	iumler	
Property in Sec.	\$ T R		/ / Ca		1008	004	
4. Lot No , Rec	corded Plat		- ABC	D E F (JKL	W
5. Private Claims					<u> </u>	iii	
		•	2 6	- 5	┝╡┵		
			3		+	, 	
Norman I Oaha	Santanh	or 3 9/1	4		-10-	_0-	2_
Norman L. Ochs in a field survey on September 3 1994 4 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			5			+++	\vdash
		r 1970, the corner points mentioned rules therefore as required in the	6 18	-1716	15	—¦4—}¦:	3
	-	nent of the Interior, Bureau of Land	7				_
		points mentioned in lines 3, 4 and 5	8 19	_2021	22	_232	4
		Land Surveyors or by a Decree of a onumented, recovered, found as	9			$\perp \perp \perp \perp$	
expressed below:	estabasiled, mondificated, re-m	onamented, recovered, todita as	10 30	-2928	27	_26]	5
NOTE: Not more than 4 core	ners all in the same town and	f range, may be recorded	11	\bot		\bot	
on this certificate. NW Corner, Sec. 1	•	-	12 31-	-3233	34	35 3	6—
A. Description of original mo	- ·	· ·	13	 			
G.L.O. John Hodgs 10" B. Oak S20°E	on 1837 #1	NCRC Sheet W. Oak NW 46.5'	#3 5 ' #4				
Ralph A. Smith RL	S #342 1	Dec. 16, 1963 Ro LCRC #86					
W. Oak NW 46.5' #: USGS Mon SW 41.5'		Found red brick. & crockery ar	ound.			ken gl	lass
	· .	Set 5" Sq. reinf 10" W. Pine N57°	E 74.85	#5)L1 .	-ovi	ER-
B. Description of corner evid	dence found and/or method a	oplied in restoring or reestablishing	corner:				

Found 5" square conc. mon set by R. A. Griffin RLS #13584. Condition of witnesses are No. 1, 2, 3, and 7 are gone. No. 8 is now a stump, No. 4, 5, 6 are good.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 5" square conc. mon 2' deep, and îs accepted as a careful and faithful reestablishment of the position of the original corner.

10" W. Pine S51°E 78.83' Spk. on SW side. #6

15" W. Pine N57°E 74.84' Spk. on SE sîde. #5

Center of USGS mon. S51°W 41.48' Cen #4

8" Red Oak 40.99' Spk. on N. side.

ochs 0chs Signed by Norman

October 19, 1994 Date ...

, 15974 APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

22439 FO LAND

22439 Surveyor's Michigan License No. 22439
Approved by Peer Review Group on November 10 Approved by reer Neview Clark Norman L. Ochs, County Representative.

> SURVEY & REMONUMENTATION

> > JEC 0 7 2000

A cont.

8" W. Pine S51°E 78.80' #6
USGS Mon. elev. 800.0' S51°W 41.48' #4
6" x 7' Cedar Post S51°W 42.90' #7
13"-16" Tw. W. Oak N30°W 47.35' #8
(Stump now)

Patrick A. Salisbury RLS #13594
June 1969
Found 5' Sq. reinforced conc. mon.
10" W. Pine N57°E 74.85' #5
8" W. Pine S51°E 78.8' #6
USGS Mon. S51°W 41.48'#4
Measured 5295.23 ft. from the NW cor to the NE cor. of Sec. 11.

May 26, 1977 Newaygo Eng. & Survey Co. Fnd. 5" Sq. conc. mon. 10" W. Pine N57°E 74.85' #5 8" W. Pine S51°E 78.80' #6 USGS Mon. elev. 800.0' S51°W 41.48' #4 6" x 7' Cedar Post S51°W 42.90' #7 Measured 2677.54 ft. from the NW cor. to the W-1/4 cor. of Sec. 11. Measured 2586.38 ft. from the SW cor. to the W-1/4 cor. of Sec. 2. Measured 2647.34 ft. from the NW cor to the N-1/4 cor. of Sec. 11.

See recorded survey in Series I, No. 482.

SUBVEY & REMONUMENTATION

JEC 0 7 2000

TECTION