

MAR 0 2 1999

SECTION

16" Maple N14°W 30.53' #7

1998 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3

For corners in Newaygo (County)	Located in:	Corner Code #	Lin	as M. Bu
Public Land Survey	T <u>12N</u> R <u>14W</u> T R T R	B-1	YOL. $oldsymbol{2}$	184
 Property Controlling in Section Miscellaneous Property in Sec. 	STR STR STR STR		Register of Deeds Stamp &	File Number
do hereby certify that under req	rded Plat, in a field survey on July 8 uirements of P. A. 74, Michigan P.A. of 16 2 above were in conformance with regulati	970, the corner	2 - 6 - 5 - 4 - 3	H I J K L M B + 2 + 1 - 0 + 11 + 12 -
Department of the Interior, Bure Law and/or that the corner po conformance with the rules or	rent manual of survey instructions of the eau of Land Management or by a decree oints mentioned in lines 3, 4 and 5 ab the Michigan Board of Land Survey olished, re-established, monumented, received.	e of a Court of cove were in yors or by a	6 18 - 17 - 16 - 1 7 - 19 - 20 - 21 - 2 9 - 19 - 20 - 21 - 2	
Note: Not more than 4 recorded on this	corners, all in the same town a certificate.	nd range, may be	10 30 + 29 + 28 + 2 11 12 31 + 32 + 33 + 3	
North One Quarter Corner,	Section 6, Sheridan Township, Newa	aygo County, Michigar		

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Not set Lyle S. Shepherd R.L.S. #503 Book 84 Page 29 1950 Newaygo County Road Commission Sheet Bolt in pavement Bolt in pavement South One Quarter Corner, Section 33, T13N R14W, East 28.4' #1 Telephone Pole N15°E 42.4' #2 Michigan Highway Department Fence Post North 33.0' #3 Bolt in pavement 1928 ± Fence Corner N70°E 84.63' #4 Norman L. Ochs R.L.S. #22439 Fence Corner S33°E 40.22' #5 Drawing Number 77150AC October 7, 1977 18" Stump N40°W 47.72' #6

Found Monument Box 11/2" Pipe Fence Corner N70°E 84.63' #4 Fence Corner S33°E 40.22' #5

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 11/2" X 22" Iron Pipe in monument box on line ± with tree row extended North and the centerline of the East and West bituminous road is 5 feet South. The condition of the recorded witnesses are: #1 good condition, #2 thru #6 gone, #7 thru #10 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Iron Pipe and monument box and set a 23/2" X 20" Harrison cast iron monument marked "County Survey" in new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful

eestablishment of the original position for the North One Quarter Corner.	
South One Quarter Corner, Section 31, T13N R14W (2¾" X 20" Harrison cast iron monument in West 28.40' #1	monument box)
/vest 26.40 #1	
34" Maple N13°W 30.42' Found nail with tag #30389 in West side of tree, #7	OF WICE
12" - 14" Twin Birch N32°E 62.60' to centerline #8	A DE WICH

Power Pole S56°E 95.58' Found P.K. nail with tag #30389 in Northeasterly side of pole. #9 Southwest Corner House Foundation #9199 N03°W 104.78' #10 Service Pole N75%E 123.22' Set spike with tag #22439 in South side of pole.

signed by / //omn/n	\mathcal{L}	Date	October 15,	1998 3
Norman L. Ochs				
Surveyor's Michigan License No	22439	Form an	proved by Michigan St	ate Board of Land Su

Approved by Peer Review Group on October 22, 1998 Norman L. Ochs, County Representative.



Revised Why.

Revised Jan.,

A. Description (cont.)

William Fries, Jr. R.L.S. #30389 LCRC #780 January 8, 1987

Found Monument Box. Box is in West bound lane of Highway M-82. Corner is 17 feet West of fence to the South and is 3 feet North of the occupied centerline of the East and West highway.

6"-9" Twin Birch N27°E 62.69' #8

Power Pole S61°E 95.51' #9

Monument Box Corner B13 (South One Quarter Corner, Section 31, T13N R14W) West 28.61' #1

25" Maple N21°W 30,43' #7

Southwest Corner House #9199 Foundation N09°W 104.93' #10

SURVEY & REMONUMENTATION

MAR 0 2 1999

SECTION