

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY...
REGISTER OF DEEDS
LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code#		Lind	שאוז.	Brow
1. Public Land Survey	T <u>12N</u> R <u>14W</u> T R T R T R	<u> </u>	vol. 1	PAGE	23	3
Property Controlling in Section	STR STR					
3. Miscellaneous	STR	***************************************				
Property in Sec.	STR	Re	gister of Deeds			
		•	A B C 1	DE F G	II t J	KLM
4. Lot No, Recor	ded Plat		2			
5. Private Claims	The state of the s			'	1-1-1	
			3		- -	-
i Normani Osha	in a field survey on October 3	40.00	1 _ }	·	10-1-11-	
	irements of P. A. 74, Michigan P.		Б			_ _ _
	2 above were in conformance with					
•	ent manual of survey instructions	•	G - (0 - 1 - 1)	7	15-1-14	
	au of Land Management or by a		7		- -	
•	ints mentioned in lines 3, 4 and		0	0	-72-1-27	
	the Michigan Board of Land				ŦŦŦ	
recovered, found as expressed b	lished, re-established, monument	tea, re-monumentea,		- - -	1-1-1-	
recovered, found as expressed b	elow.	`	10 -302	9	-2728	
Note: Not more than 4	4 corners, all in the same tow	town and range, may be	"		- -	_
recorded on this		to the analysis, may be	12313	2	.04 05	
recorded on this	coranogie,		13		1.1.1	
Southwest Comer, Section	on 17, Sheridan Township,	Newaygo County, Michigan	n	•	•	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John H. Mullett 1838 8" Tamarack N65°W 14 Links (9.24')#1 8" Tamarack S47°E 34 Links (22.44')#2

Delos G. Anderson (County Surveyor)
Book A Page's 225 and 226 May 2 and 3, 1898
Old Government corner in marsh

William Fries, Jr. R.L.S. #30389 Found 1¼" Pipe LCRC #708 January 20, 1986 10" Elm N08°E 89.91' #7 7" Elm S79°E 26.91' #8 1 1/8" Iron in monument box South 1,321.51' #9 Patrick A. Salisbury R.L.S. #13594
Found %" Pipe December 13, 1974
Square Telephone box ±2' Above ground East 17.55' #3
24" Corregated Metal Pipe N30°E 21.58' #4
24" Corregated Metal Pipe N30°W 21.68' #5
15" Corregated Metal Pipe West 39.30' #6

5" Double Elm S72°W 81.62' #10
Apparently subsequently restored by unknown surveyor. Used corner as found as perpetuation of original corner. Found 1¼" Pipe 6 feet North of occupied centerline of road to the West and in occupied centerline of North and South road.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 3/4" Pipe in centerline of North and South road and fence going East is 3 feet South and the condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 and #5 new pipe, #6 good condition, #7 gone, #8 and #9 good condition, #10 dead.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed %" Pipe and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

coston como ana la acceptad de a carcia, ana ladada recotablishinos el alc eliginar conter.				
Square Telephone box ±2' Above ground East 17,93' #3	Of MICH			
15" Corregated Metal Pipe West 40.0"#6	A. P. Carrier and			
14" Elm S79°E 26.91' Set spike with tag 26.91' #8	NORMAN NORMAN			
1 1/8" Iron in monument box South 1,321,50' #9	L. OCHS			
8"-8" Double S70°W 58.74' Set spike with tag in Southeast side of tree.				
24" Corregated Metal Pipe N50°E 25.91'				
24" Corregated Metal-Pipe N40°W 27.55'	No.			
\mathcal{L}	22439			
Signed by Aman & Chos Date October 17, 1996	10			
Norman L. Ochs	A LAND OF THE PARTY OF THE PART			
Surveyor's Michigan License No. 22439 Form approved by Michigan State	Board of Land Surveyors, Jan 28, 1971			
	Revised May 14, 1975			
Approved by Peer Review Group On	Revised Jan., 1983			

Norman L. Ochs, County Representative.