MAR 1 3 2000

NEWAYGO COUNTY REGISTER OF DEEDS

1999 Newaygo County Remonumentation Project LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATED FEB 28 PM 1 11 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

vol. 2	333
of Deeds Stamp & File No	umber
18 + 17 + 16 + 15 + 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	13
	
	B C D E F G H 1 J 6 + 5 + 4 + 3 + 2 1 + 1 + 1 + 1 7 + 8 + 9 + 10 + 11 18 + 17 + 16 + 15 + 14

A. DESCRIPTION OF ORIGINAL MONUMENT AND AC

G.L.O. John Hodgson 1837 10" Black Oak N60°W 105 Links (69.3')#1 8" Black Oak N601/2"W 117 Links (77.22')#2

Winfield S. Merrill (County Surveyor) March 8, 1882 Book A, Page 61 Measured 39.98 Chains (2638.68') from the Southeast Corner to the South One Quarter Corner of Section 25.

Lyle S. Shepherd R.L.S. #503 July 11, 1930 Book 71, Page 105 Measured 5479.4 feet from the Northwest Corner to the Northeast Corner, Section 31, T13N R11W.

Winfield S. Merrill (County Surveyor) February 17, 1882 Book A, Page's 55 and 56 7" Yellow Oak \$54°E 9 Links (5.94')#3 14" Yellow Oak N29°W 80 Links (52.8')#4

Lyle S. Shepherd R.L.S. #503 August 30, 1916 Book 36, Page 88 and Witness Book Number 2, Pages 30 and 46 Found old corner and bearing trees. Planted a stake, Buggy Axle and stone. Centerline of Tower East 44.5' #5 10" Black Oak S41%°W 39' #6 20" Black Oak N28°W 52' #4 Consumer's Power Pole N55°W 41.5' #7

OVER 🗞

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" diameter Harrison cast iron monument marked "County Surveyor" 6 inches ± below grade, on line ± with the centerline of bituminous road to the North extended South, on line \pm with the centerline of gravel road to the South extended North and on line ± with the centerline of bituminous road to the West extended East. The centerline of gravel road going Northwest -Southeast is 42 feet ± West and there is no apparent occupation to the East. The condition of the recorded witnesses are: #1 thru #4 gone, #5 good condition, #6 thru #8 gone, #9 good condition, #10 gone, #11 good condition, #12 gone, #13 thru #15 did not measure, #16 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" diameter Harrison cast iron monument marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

alla la accobica ac a calleral ana rannia i socialisti di se		•	OF MICANIA
Centerline of North and South Tower line East 44.5' #5			ALL COMMENTS
Cut "A" in Southwest leg to Steel Tower (3'± above grade) N18	8°E 140.8	31' #9	NORMAN
Power Pole S62°W 100.13' Found spike in South side of pole	, #1 1		L OCHS *
14" White Pine (blazed) N64°E 108.27' Found spike in South	side of tr	ee. #16	A LAND
12" White Pine (blazed) N35°W 78.82' Set spike with tag #22	439 in Ea	ast side of tree.	SURVEYOR C
\mathcal{A}			22439
Signed by // Mman L. Chhs	Date	November 26, 1999	22402
Norman L. Ochs	_		TO LAND
Surveyor's Michigan License No. 22439	Form app	roved by Michigan State Board of	Land Surveyor Change Control
	, -		Revised May 14, 1975
Approved by Peer Review Group on November 30, 1999			Revised Jan., 1983
Norman L. Ochs, County Representative.			

11. 20

A. Description (cont.)

Lyle S. Shepherd R.L.S. #503 August 22, 1934 Book B, Page's 88 and 89 and Book 70A, Page 7 Ford Axle SURVEY & REMONUMENTATION

Nikel (United States Forest Service) 1936 Well Point 3" below ground Oak Post North 50 Links (33')#8 MAR 1 3 2000

SECTION

Raiph A. Smith R.L.S. #3421 Book 46 A, Page 8 and Witness Book Number 2, Page 30 Axle Shaft Power Pole N55°W 41.5' #7 Southwest leg of Tower N20°E 140.8' #9

Ralph A. Smith R.L.S. #3421
April 30, 1954 Book 70A, Pages 59 and 60
Buggy Axle and broken glass found, set a ¾" Pipe
12" Twin Black or White Oak N65°W 102.9' #10
Southwest leg of Tower N20°E 140.8' #9
Power Pole S64°W 99.8' #11
Consumers Power Tower N18°E 140.9' #9

Newaygo County Road Commission Sheet Axle Shaft (2) 12" Oak N61°W 72.8' #12 Power Pole S64°W 99.8' #11 Consumers Power Tower N18°E 140.9' #9

Patrick A. Salisbury R.L.S. #13594
March 28, 1967 Book 90, Page 14
"Hefner's Plat" Recorded in Liber 4 of plats, Page 24
Found 1" Pipe ± at point of intersection of road
Southwest Corner Tower N18°E 140.86' #9
18" Twin White Oak N35°W 103.05' #10
Power Pole S64°W 100.05' #11
Point of curve West 559.7' #13
Point of tangent North 559.7' #14

Patrick A. Salisbury R.L.S. #13594
"Hefner's Plat Number 2" February 20, 1970 Recorded in Liber 9 of plats, Page's 2 and 3
Southeast Corner of plat is S88°39'W 1306.71' #15

Norman L. Ochs R.L.S. #22439 April 27, 1976 Drawing Number 76041AC 1" Pipe Southwest Corner Tower N18°E 140.86' #9 18" Twin White Oak N35°W 103.05' #10

Norman L. Ochs R.L.S. #22439
October 18, 1989 Found 1" Pipe at point of intersection of road Southwest Corner Tower #429978 N18°E 140.80' #9
18" - 30" Twin White Oak N35°W 103.76' #10
Power Pole S64°W 100.07' #11

Norman L. Ochs R.L.S. #22439

December 21, 1990 LCRC #1067 Corner is at point of intersection of road

Found ½" Pipe, removed and set a 4" diameter Harrison cast iron monument marked "County Surveyor"

12" White Pine N45°E 108.23' #16

Southwest Corner Tower N18°E 140.45' about 2 feet above ground. #9

18" - 30" Twin White Oak N35°W 103.22' #10

Power Pole S64°W 100.12' #11

William Fries, Jr. R.L.S. #30389

November 14, 1996 Recorded in Liber 366, Page 7468

Cast iron monument

12" White Pine N45°E 108.23' #15

Southwest Corner Tower N18°E 140.45' about 2 feet above ground #9

18" - 30" Twin White Oak N35°W 103.22' #10

Power Pole S64°W 100.12' #11