SURVEY & REMONUMENTATION

NEWAYGO COUNTY REGISTER OF DEEDS

1998 Newaygo County Remonumentation Project

LINDA M. BROWN

MAR 0 2 1999

LAND CORNER RECORDATION CERTIFICATE '99 FEB 17 PM 3 39 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code #	Linda M.	Drown
1. Public Land Survey	T <u>13N</u> R <u>11W</u> T R T R	<u>C-1</u>	VOL. $oldsymbol{2}$	233
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR		Register of Deeds_Stamp & F	ile Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poiconformance with the rules of	_, in a field survey on <u>October 22</u> irements of P. A. 74, Michigan P.A. above were in conformance with regard manual of survey instructions of au of Land Management or by a dints mentioned in lines 3, 4 and 5 the Michigan Board of Land S ished, re-established, monumented	of 1970, the corner gulations and rules the United States ecree of a Court of 5 above were in surveyors or by a	A B D E F G H 2 - 6 - 5 - 4 - 3 - 3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9	2 - 1 - 11 - 12 - 14 - 13 -
Note: Not more than 4 o recorded on this c	orners, all in the same towertificate.	vn and range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
Northwest Corner, Section 5,	Big Prairie Township, Newaygo	County, Michigan.	13	
<u> </u>				

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 24" Pine S46°W 17 Links (11.22')#1 24" Pine S74°E 39 Links (25.74')#2

Newaygo County Road Commission Sheet Reinforced Rod 18" Black Oak S42°W 90.2' #5 Power Pole N47°W 48.00' #6 16" White Oak N65°E 51.2' #7

Robert A. Griffin R.L.S. #13584 1977 Found "P.K." spike in pavement Southeast Corner, Section 31, T14N R11W, (½" Pipe) East 19.68' #10 Lyle S. Shepherd R.L.S. #503 Book 95 Page 27 1922 2" Wood Stake 10" Oak N51°30'E 35.2' #3 24" Oak S25°30'W 132.5' #4

Patrick A. Salisbury R.L.S. #13594 October 16, 1972 Found ½" Rod Southeast Corner, Section 31, T14N R11W East 19.68' #10 Power Pole N50°W 48.39' #6 12" Pine S40°E 42.36' #8 Guy Pole S45°W 56.49' #9

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" X 18" Rerod next to a ½" (on top) X 24" (1" on bottom) Rod that was thru an old steel Axle Mount on line ± with the centerline of the East and West bituminous road and on line ± with the centerline of the gravel road going South. The condition of the recorded witnesses are: #1 thru #4 gone, #5 stump, #6 good condition, #7 and #8 gone, #9 and #10 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rerod, Rod and Axle Mount and set a 2¾" X 20" Harrison cast iron monument marked "County Survey" in new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole N47°W 48.35' Found spike in Northeasterly side of pole (also Forest Service local Guy Pole S46°W 56.51' Found spike in Southeasterly side of pole (also Forest Service located)	ator Poster) #6
Southwest Corner, Section 32, T14N R11W, East 19.68' #10	MMMMM
20" Red Pine S40°E 60.37' Found spike in Northeasterly side of tree. ½" Rerod N57°E 62.31'	OF MIC
24" - 26" Twin Black Oak N68°E 106.20' Set spike with tag #22439 in South side of tree.	NORMAN L. OCHS

Signed by // V/14cm/ V	·	Date	November 3, 1998
Norman L. Ochs		-	
Surveyor's Michigan License No	22439	Form appro	oved by Michigan State Board of L

Approved by Peer Review Group on ______ December 8, 1998

Norman L. Ochs, County Representative.

Adeliaceyors 180 g8, 197 Selved May 14 987 Repsed 181, 198