1993 NEWAYGO COUNTY REMONUMENTATION PROJECT EWAYGO COUNTY REGISTER OF DEEDS MARLENE TOOGOOD

PED LAND

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 Revised May 14, 1975 Revised Jan., 1983

Date November 8, 1993

LAND CORNER RECORDATION CERTIFICATE 94 JAN 21 PM 3 26 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Marlone Toogood NEWAYGO Located In: Corner Code =## $_{\rm T}13N$ $_{\rm R}12W$ Public Land Survey VIIL 001 PAGE 21 R Æ ·R Property Controlling R in Section s R Miscellaneous S R Register of Deeds Stamp & File Number Property in Sec. s R _ , Recorded Plat 5. Private Claims _ I. Norman L. Ochs , in a field survey on November 1 , 19 93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawand/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. NW Corner, Sec Everett : Twp., Newaygo County, MT Description of original monument and accessories and/or subsequent restoration on:
1973 R A Griffin LCRC #691
5" Sq x 36" conc mon C.Cole #17615
5" W Oak N51°E 89.26' #9 See L. 349
8" W Oak S27°E 49.50' #10 Also Pg.2698
17" R Pine S55°W 61.89' #11
4"x7" Post N 33.26' #12 Oct 1958 R A Smith 3/4" Pipe 18" Pine S80°W 61.8' #6 17" W Oak N25°E 66.6' #7 10" B Oak N45°W 66.1' #8 GLO John Hodgson 1837 16" Pine WELW 16 1ks : #1 19" Pine S33°E 16'1ks : #2 C.Cole #17615 See L. 349 1938 R A Smith Gas Pipe 24" B Oak S+ 32.4' #3 15" Pine S55°W 61.7' # Nov 1975 DNR 5" sq. x 86" conc mon Same witnesses as R A Griffin in 1973 15" Pine S55°W 61.7" #4 14" W Oak N25°E 67.2' #5 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

/find. gas pipe by R. A. Smith

R. A. Griffin in 1973 set 5" sq. x 36" conc. mon, 3-1/2" North of CL of East and West road.

Found Griffins conc. mon. in good condition raised with 1/2" rod 6" long. Condition of recorded witnesses is: #1 gone, #2 gone, #3 gone, #4 good condition, #5 g condition, #6, gone, #7 good condition, #8 gone, #9 good condition, #10 good condition, #11 good condition, #12 gone. #5 good C. Description of morphent for corner and accessories established to perpetuate locating the position of the corner. Accepted R. A. Griffins conc. mon. raised with 1/2" rod 6" long as a substantial marker for the Section corner, and is accepted as a careful and faithful reestablishment of the position of the original corner. of alcale 20" W. Oak N25°E 67.47' Spk. #5, #7 6" W. Oak N51°E 89.26' Spk. #9 12" W. Oak S27°E 49.50' Spk. #10 20" W. Pine S55°W 61.80' 1/4" iron in tree #6, #11 NORMAN L: OCHS land Survey**or** 22439

9, 1993

SURVEY & REMONIMENTATION

Approved by Peer Review Group Nov. 9 Norman L. Ochs, County Representative

Norman L. Ochs Surveyor's Michigan License No.

DEC 07 2000

POTION