MAY 2 8 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '97 FEB 12 PM 4 4!

For corners in Newaygo (County)	Located in:	Corner Code#	•.	Sin	sa VII.	Brow
Public Land Survey	T <u>13N</u> R <u>12W</u> T <u>13N</u> R <u>13W</u> T R T R	M-5	VOL. 1	PAGE	241	
Property Controlling in Section	STR					
3. Miscellaneous Property in Sec.	\$R		Register of Deeds Stamp & File Number			
4 Let No Bees	anded Diet		A B	0 0 8 8	0 11 1 ,	<u> —</u> Укім
4. Lot No, Reco	proed Plat		,			
			ا ا ا	-1-1-1-	-	१− - -
	•				- -	<u> - - -</u>
I, Norman L. Ochs	, in a field survey on <u>December 17</u> uirements of P. A. 74, Michigan P.A. of 197	, 19 <u>96</u> ,	1-1-	-1-1-1-		1
points mentioned in lines 1 and	2 above were in conformance with regulation	v, the comer is and rules	9	_ -	-	
therefore as required in the cur	rent manual of survey instructions of the Ur	nited States	6 18		- 5	4
Department of the Interior, Bure	eau of Land Management or by a decree of	of a Court of	` 7]			<u> _ </u>
	pints mentioned in lines 3, 4 and 5 abov f the Michigan Board of Land Surveyo		019	-2021-	_	
	blished, re-established, monumented, re-m		9 <u> </u>		Î	
recovered, found as expressed		1011011011004	10 10			
N 4 N 4 41 4		**		2020-	27 2	825-
Note: Not more than 4 recorded on this	corners, all in the same town a certificate.	nd range, may be	12 _31_	-3233-	343	5
	•		13			
Southwest Comer, Secti-	on 7, Everett Township, Newaygo	County, Michigan	1	•		

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John H. Mullett 1837 12" Hemlock N76°E 18 Links (11.88')#1 12" Hemlock \$44°E 36 Links (23.76')#2

Lyle S. Shepherd R.L.S. #503 Witness Book Number 2 Page 32 4" Oak S40°±E 63.5' #3 Ash West 24.7' #4

Patrick A. Salisbury R.L.S. #13594 March 20, 1972 Set 1/2" rerod by old witnesses 6' West of centerline road to North 36" White Pine N78°30'E 172.70' #5 4"-8" White Oak S32°E 65.46' #3 12" White Oak S20°W 34.17' #6

Newaygo Engineering and Survey Company LCRC # 1161 December 5, 1992 Found ¾" Iron Pipe by using 1972 witnesses. Removed and set 4" diameter Harrison cast iron monument 10" Red Pine N53°W 26.67' #7 18" White Oak S11°W 33.98' #6 Clump of 4 12" White Oak S32°E 65.39' #3 Clump of 4 ± 6" to 18" Maple S75°E 88.62' #8

Southeast Corner, Section 12, Sherman Township, Newaygo County, Michigan

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" diameter Harrison cast iron monument and the centerline of the North and South dirt road is 5 feet East and the centerline of the East and West trail road is 6 feet North and the condition of the recorded witnesses are: #1 thru #3 gone, #4 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4 diameter names on cast iron monument 35" long marks		marker for the section corner and
is accepted as a careful and faithful reestablishment of the original	corner.	
4"-6" Twin Ash West 24.7' to face of tree. #4 36" White Pine (dead) N82°E 172.70' Found spike in North side of 22" White Oak S25°W 33.98' Found spike in West side of tree. #6 12" Red Pine N50°W 26.61' Found spike with tag #22439 in South 6"-6"-12"-22" Quadruple Maple S72°E 88.62' Found spike in South	tree. #5 nwest side of tree. #7	NORMAN L. OCHS LAND SURVEYOR
12"-20"-12"-20" Quadruple White Oak S26°E 65.42' Found spike i	n Northeast side of tree.	Ho.
$\mathcal{A}(\mathcal{A}(\mathcal{A}))$		22439
Signed by florman L. Ocho	DateDecember 20, 1996	
Norman L. Ochs		LAND SEE
Surveyor's Michigan License No22439	Form approved by Michigan State Board	of Land Surveyors, ball 28, 1971
		Revised May 14, 1975
Approved by Peer Review Group On <u>December 23, 1996</u>	•	Revised Jan., 1983
Norman I Oaks County Bonrocentation		