MAR 1 3 2000

SECTION

NEWAYGO COUNTY

1999 Newaygo County Remonumentation Project REGISTER OF DEEDS

LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT of Act 74, Mich. P.A. 1970 (1) FFR 28 PM 1 10

			0016820	
For corners in Newaygo (County)	Located in:	Corner Code #	Linds M	. Brown
1. Public Land Survey	T <u>13N</u> R <u>12W</u> T <u>13N</u> R <u>13W</u> T R T R	A-10	$^{\circ}$ YOL. $oldsymbol{2}$	316
Property Controlling In Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp &	File Number
			register of Deeds Staffip &	rile Number
4. Lot No. , Record 5. Private Claims , Record 6. Private Claims , Norman L. Ochs do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curred Department of the interior, Burest Law and/or that the corner policonformance with the rules of Decree of a Court of Law, establing recovered, found as expressed by	, in a field survey onAugust lirements of P. A. 74, Michigan F. above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 the Michigan Board of Land lished, re-established, monume	P.A. of 1970, the corner in regulations and rules is of the United States a decree of a Court of and 5 above were in it Surveyors or by a	A B C D E F G H 2 - 6 - 5 - 4 - 3 3 - 1 - 1 - 16 - 15 7 - 18 - 17 - 16 - 15 7 - 19 - 20 - 21 - 22 9 - 1 - 1 - 1	- 2 - 1 - - 11 - 12 - - 14 - 13 -
Note: Not more than 4 c recorded on this c	orners, all in the same tertificate.	town and range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	+++-
West One Quarter Corner, S East One Quarter Corner, Se	ection 30, Everett Township, ection 25, Sherman Townshi	, Newaygo County, Michigan. p, Newaygo County, Michigan		35 + 36 -
A. DESCRIPTION OF OF	RIGINAL MONUMENT AI	ND ACCESSORIES AND/	OR SUBSEQUENT RESTO	RATION:
G.L.O. John Hodgson 18				

8" White Oak S61°W 57 Links (37.62')#1 8" White Oak N25°W 28 Links (18.48')#2

Lyle S. Shepherd R.L.S. #503 Witness Book Number 2, Page 32 Approximately early 1900's 40" Pine Stump N57°E 8' #3

Patrick R. Leemon R.L.S. #31595 1993 11/2" Pipe 32" Pine Stump Northeast 8.2' #3 8" Maple Southwest 31.76' #5 15" Oak Southeast 19.21' #6 8" Twin Oak North 43.74' #4

Newaygo County Road Commission Sheet Pump Handle 40" Pine Stump N57°E 8' #3

Donald W. Schiele R.L.S. #32517 LCRC #489 August 10, 1978 Recorded in Series I, Number 9994 Found 11/4" Iron Pipe 8" Twin Oak North 43.74' #4 15" Oak Southeast 19.21' #6 8" Maple Southwest 31.76' #5 Centerline 32" Pine Stump Northeast 8.2' #3

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Pump Handle and old Well point and the centerline of the North and South two-track in pole line is 44 feet ± East. There is no apparent occupation North, South or West. The condition of the recorded witnesses are: #1 and #2 gone, #3 stump, #4 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Pump Handle and Well point and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablished

	corner.
40" Pine Stump N45°E 8.3' ± to centerline. #3 10"-14" Twin Black Oak N07°W 43.97' Set spike with tag #22. 16" Maple S43°W 31.78' Set spike with tag #22439 in Northw 24" Black Oak S55°E 19.27' Set spike with tag #22439 in Sou 24"-20" Twin Black Oak N17°E 32.44' Set spike with tag #224	esterly side of tree. #5 thwesterly side of tree. #5 L. OCHS
Signed by Moman F. Ocho	_ DateAugust 16, 1999
Norman L. Ochs	The second secon
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyor 1971
Approved by Peer Review Group on October 28, 1999	Revised May 14, 1975
Norman L. Ochs, County Representative.	Revised Jan., 1983
n. L.O	