1993 NEWAYGO COUNTY REMONUMENTATION PROJECTISTER OF DEEDS MARLEHE TOOGOOD

## COMMISSION LAND CORNER RECORDATION CERTIFICATE PM 3 26

_		Filing Requirement of Act 74, Mich. P.A. 1970					
FOI	corners in			,	\ 400 N		а
	NEWAYGO	Located	in: .	Corner Code ##	Marle	na 1000	9,004
	(County)						•
	Public Land Survey	- 13N	R 12W	<u>I-1</u>		·	
١.	rubiic Lanu Survey		R			MA	94
					VOL	001 PA	of J1
			R			<del></del>	- '
			R				
2.	Property Controlling	S T	_ R				
	in Section	S T					
3.	Miscellaneous	S T			Register o	of Deeds Star	np & File Number
	Property in Sec.	S T	_ R				<u></u>
4.	Lot No ,	Recorded Plat			A	BCDE	F G H 1 J K L M
						<u> </u>	
					2 ├─	65	4 - 1 - 1 - 1
					3		
					4		9 10 11 12
, 1	Norman L. Ochs	in a field survey	Decemb	<u>er 16 , <sub>19</sub> 93 </u>	, 5	i Ti I Ti	ĭIïIïI
4, _	nereby certify that under r	_ , in a new survey of requirements of P.A. 74	Michigan P.A. of	1970, the corner points ment	tioned		
				ules therefore as required		18	16-15-14-13-1
				ent of the Interior, Bureau of		╀┉╂┈┼	+
				oints mentioned in lines 3, 4		19	21 22 23 24
abo	ve were in conformance	with the rules of the Mir	chigan Board of L	and Surveyors or by a Decre	ee of a 9		
		, re-established, mon	umented, re-mo	numented, recovered, fou	nd as		<u>]                                    </u>
	ressed below:				[ '	30-1-29-2	28 27 26 25
NO	TE: Not more than 4	corners, all in the s	same town and	range, may be recorded	11	<del>                                     </del>	<del>\                                    </del>
	on this certificat	e.			12	3132	3/3 3/4 3/5 3/6
W. (	Corner, Section	2, Everett Twp	., Newaygo	County, Michigan	13 🖳		
Α.	Description of origina	al monument and acc	cessories and/o	or subsequent restoration	n: **		
G	L.O.			e S. Shepherd's W			
	Pine N41 W 16 1	ks. (10.56')#1	lro	on by Ralph A. Sm	ith K.L.S.#3	421	
1911	Pine S33°E 16 1	ks (10.56')#2	127 Ma	ple S72 E 85.7 #	£4		
الربيد	1 OT 4 CCC 2011 1	NO. (10.50 )7FZ	16'' Oa	ple S72 <sup>0</sup> È 85.7' <i>1</i> nk N66 E 75.4' <i>#</i> 5 ple N34 W 44.10'			
Do.	los C. Anderson	October 1898	10'' Ma	uple N34~W 44.10'	<i>#</i> 6		•
2/11	los G. Anderson Pine Stump S51º	ta 83 11ca /5/	78 ! \ #3				
24 Do -1	THE SCHID SOF	и оэ шкs. (э4.	70 <u>)</u> 3F3				
ROOI	k A Pages 239 an	.d 240	N.C.R.	C. Sheet	1011 Man	le N34 <sup>0</sup> W (	1.1. 11 316
			Tron		<del>-</del>		
			12" Map]	.e S72 <sup>O</sup> E 85.7' #4	16'' 0ak	N66°E 75	.4 <b>'</b> #5
R	Description of corner	evidence found and		plied in restoring or rees			
٥.	Boodinption of collies		.,		J		
In	1898 Delos G. An	derson did a s	ection brea	ak of Sec. 2. Ande	erson measur	ed 80.37 (	chains (5304.42')
from	the NW. Corner	to the NE. Cor	ner and mea	sured 79.17 chair	ns (5225.22	feet) fro	m the NW. Corner
-n +1	na SW Corner T	n 1915 Ivle S	Shenberd r	neasured 160.675 d	hains (10 f	04 55 feet	t) from the NW.
							und in field book
94 page 38 at the County Surveyor's Office. In 1963 Ralph A. Smith did a section break of Sec. 2, Everett Twp. Smith measured N88°13'30"E 2650.20 feet from the NW. Corner to the N. 1/4 Corner and							
ver	SEE IWD. SINLLII II	easured Noo 13	SO E ZOJO.	ZU reer from the	INW. COLLIEL	to the N.	oformation was
measured S00°11'49'W 2587.37 feet from the NW. Corner to the W. 1/4 Corner. This information was							
found in field book 81B Page 46 at the Newaygo County Surveyor's Office. Found 1/2" Pipe. Replaced with 4" Harrison Cast Iron Monument.							
oun	1/2 Pipe. Rep	laced with 4"	Harrison Ca	ast Iron Monument.			
Condition of recorded witnesses is; #1 thru #3 Gone #4 thru #6 Good Condition							
C.	Description of monur	nent for corner and a	accessories est	tablished to perpetuate I	ocating the posit	tion of the co	rner:
1000	nted /!! Harricen	Cast Iton Mon	n mont se s	substantial marke	er for the s	ection co	rner and is
				shment of the original			LIKE CIKI TO
acce	pled as a carero	T and farming	. reescaurts	numeric of the orig	Smar corner		Marie Sant
110 F	M-1- 070011 06	071 G-85- A- 6	0		-a	ع	OF MICH
TO	Maple S/u L 86.	27 Spike in t	ree z reet	more or less abov	e ground 174		A The resessor of the second
7. P	ole N12 <sup>O</sup> E 31.82'	Spike in West	side of po	ore		£.,	🥻 NORMAN 🔪 🦠
₽. P	ole S30°W 97.61'	Spike in West	side of Po	or.		£ 4.	L. OCHS 🖈 🕏
ىL.	Corner concrete	telephone rise	r N56 W 55.	85.		% <b>*</b>	1A2D **
[8 <sub>i</sub> , ]	Maple Stump N34~	W 44.10' to fa	ice #6			\$ P.	SURVEYOR =
78i, 1	Corner concrete Maple Stump N34° W. Oak N66°E 76.	3 <i>' 排</i> 5				1	SURVEYOR 5
	-					7	
	ير ا	. 1 -	$\wedge$			74	O LAND
	ned by Norman L	Y 10V	. 12	ת	noombar 16	1002	MANAGE TO SERVED
Sig	ned by / COm	m. J. UX	chs_	Date	ecember 16,	1773	
	Norman L	, UCП\$ 22439					- AF   BAIR ATTENDED   1235 1450-
	veyor's Michigan Lice		Dec 1	1002	FORM APPROVED BY M	ICHIGAN STATE BOARD	OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975
	Approved by Po						REVISED JAN., 1983
]	Norman L. Ochs	s, County Re	presentat	ıve			