MAR 1 3 2000

NEWAYGO COUNTY 1999 Newaygo County Remonumentation Project REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE SECTION FILING REQUIREMENT of Act 74. Mich. P.A. 1970 On ten an

LINDA M. DROWN

For corners in		•	OU FEB 28 PI	1 1 11
Newaygo (County)	Located in:	Corner Code#	Linda YA. &	Brown
1. Public Land Survey	T <u>13N</u> R <u>12W</u> T R T R	<u>I-11</u>	•	
Property Controlling     in Section     Miscellaneous	TR STR STR STR		<b>vol. 2</b>	32
Property in Sec.	STR		Register of Deeds Stamp & File	Number
4. Lot No, Recorded Plat  5. Private Claims			1 A B C D E F G H I 2 - 6 + 5 + 4 + 3 +	J K L M
points mentioned in lines 1 and therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po	_ , in a field survey on <u>Novemb</u> .  Jirements of P. A. 74, Michigan P.  above were in conformance with ent manual of survey instructions au of Land Management or by a intermediate of the Michigan P.	A. of 1970, the corner regulations and rules of the United States	3 4 7 8 9 10 - 5 6 18 17 16 15 - 7	11 - 12 -

conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented recovered, found as expressed below: Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Northeast Corner, Section 34, Everett Township, Newaygo County, Michigan.

## 7 8 20 21 23 24 10 30 29 28 27 26 25 11 12 32 33 34 35 13

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J.H. Mullett 1837 18" Pine \$45°W 50 Links (33')#1

12" White Oak N64°W 95 Links (62.7')#2

Newaygo County Road Commission Sheet

18" Black Oak S44°W 56,75' #3 14" Twin Black Oak N21°E 50.5' #4 10" White Oak S44°E 81.9' #5

18" - 18" Twin Black Oak N21°E 51.24' #4 10" White Oak S44°E 82.03' #5

April 24, 1979

Norman L. Ochs R.L.S. #22439

West blacktop road is 1.40' North. 22" Black Oak S44°W 57,38' #3

Drawing Number 79044B

Found 5/8" Rod in monument box in centerline of road going South and in centerline of trail going North. The centerline of the East and

Norman L. Ochs R.L.S. #22439 December 5, 1990 LCRC #1073

Found 5/8" Rod in 1" Pipe in monument box. Removed and set a 4" diameter Harrison cast iron monument marked "County

22" Black Oak S44°W 57.32' #3

18" - 18" Twin Black Oak N21°E 51,30' #4

10" White Oak S44°E 82,04' #5

10" Black Oak N45°W 43.38' #6

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING

Found 4" diameter Harrison cast iron monument 16" long marked "County Surveyor" in monument box. On line ± with the centerline of gravel road going South and on line ± with the centerline of two track going North and the centerline of the East and West bituminous road is 1 foot ± North. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" diameter Harrison cast iron monument 16" long marked "County Surveyor" in 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

		•	
34" Black Oak (blazed) S42°W 57.20' Found spike in East side of tree. #3 24" - 28" Twin Black Oak (blazed) N20°E 51.34' Found spike in West side of tree. #4 14" White Oak (blazed) S44°E 82.02' Found spike in North side of tree. #5 14" Black Oak (blazed) N23°W 43.41' Found spike in West side of tree. #6		NORMAN NORMAN	
Signed by Norman L. Ochs  Norman L. Ochs  November 30, 1999		L. OCHS LAND SURVEYOR	
Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Lan	d diri	22439	, ,

Approved by Peer Review Group on Norman L. Ochs, County Representative. November 30, 1999

MOM