

MAR 1 3 2000

NEWAYGO COUNTY 1999 Newaygo County Remonumentation ProjectEGISTER OF DEEDS

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 FEB 28 PM 1 17.

LIRDA M. BROWN

| For corners in | | • | 00112220 111 1 | 4- 1 / |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|------------------------------------------------------|---------------|
| Newaygo (County) | Located in: | Corner Code# | Linda M. Brow | use) |
| 1. Public Land Survey | T <u>13N</u> R <u>13W</u> T R T R | <u>K-12</u> | 4 | |
| Property Controlling In Section | STR STR | | VOL. $oldsymbol{2}$ | 34 |
| Miscellaneous Property in Sec. | STR STR | | Register of Deeds Stamp & File N | umber |
| points mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner poconformance with the rules of | , in a field survey onOctober a uirements of P. A. 74, Michigan P.A 2 above were in conformance with re- ent manual of survey instructions of au of Land Management or by a sints mentioned in lines 3, 4 and the Michigan Board of Land tilshed, re-established monuments | A. of 1970, the corner egulations and rules of the United States decree of a Court of 1 5 above or by a | 2 | 13 - |
| Note: Not more than 4 (recorded on this c | corners, all in the same to ertificate. | wn and range, may be | 10 30 + 29 + 28 + 27 + 26 11 + 1 + 1 | |
| West One Quarter Corner, S | ection 36, Sherman Township, | , Newaygo County, Michigar | $\begin{array}{cccccccccccccccccccccccccccccccccccc$ | 36 - |
| A. DESCRIPTION OF OF | RIGINAL MONUMENT AND | ACCESSORIES AND/O | R SUBSEQUENT RESTORATION | DM: |

G.L.O. John Mullett 1838 18" Beech S49°E 35 Links (23.10')#1 18" Beech N39°W 35 Links (23.10')#2

Delos G. Anderson (County Surveyor) Information from the United States Forest Service 22" Pine Stump N381/2°E 79 Links (52.14')#3 21" Pine Stump S49°E 68 Links (44.88')#4

Norman L. Ochs R.L.S. #22439 December 12, 1978 Drawing Number 78235AC Set ½" Rod on woods line going East and on stump fence row going West and in centerline of North and South bituminous road. Power Pole N61°W 33.75' #5 Power Pole N08°W 113.77' #6 16" Poplar N87°E 27.73' #7

William Fries, Jr. R.L.S. #30389 LCRC #1202 January 5, 1994

Found 1/2" Iron in occupied centerline of the North and South road and in old fence and tree row East and West. Southwest Corner House #4380 Foundation N39°E 115.61' #8

8" Elm N87°W 61.43' #9 Power Pole N64°W 33.73' #5 Power Pole N16°W 113.68' #6

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING

Found ½" x 18" Rerod on line ± with tree and brush rows going East and West. The centerline of the North and South bituminous road is 1 foot ± West. The condition of the recorded witnesses are: #1 thru #4 gone, #5 and #6 good condition, #7 gone, #8 good condition, #9 10" Elm (dead) N87°W 61.47' found nail with tag #30389 in North side of tree

NG

| | | • · · · · · · · · · · · · · · · · · · · | 40 01 400. |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------------------------------------|------------------------------------------------------------------------------------|
| C. DESCRIPTION OF MONUMENT FOR CORNER AND A THE POSITION OF THE CORNER: | CCESSOF | RIES ESTABLISHED TO | PERPETUATE LOCATI |
| Removed Rerod and set a 4" Harrison cast iron monument 20" box as a substantial marker for the quarter corner and is a corner. | long marke ccepted as | ed "County Surveyor" in a r a careful and faithful ree | new 8" diameter monum stablishment of the origi |
| Power Pole N60°W 33.76' Found P.K. nail with tag #30389 (Power Pole N15°W 113.75' Found P.K. nail with tag #30389 Southwest Corner Foundation to frame building N40°E 115.6 10" Cherry (blazed) N76°E 36.31' Set spike with tag #22439 Signed by Norman L. Ochs | (above old | l spike) in Northeast side o de of tree. | of pole. #5 of pole. #6 of Michie |
| Approved by Peer Review Group on October 28, 1999 Norman L. Ochs, County Representative. | Form appro | oved by Michigan State Board of L | and Sufveyors, Jan 28, 1971 Revised May 34, 4975 Revised Jan,, 1983 22439 |