

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

teres as core

MAR 0 2 1999

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

*99 FFR 17 PM 3 39

| _ | | | 00125 | ři ili 5 50 |
|---|---|------------------------|---|--|
| For corners in NewaygSECTION Lo (County) | ocated in: | Corner Code # | Lind | M. Brown |
| 1. Public Land Survey T_TT | <u>13N</u> R <u>13W</u> R R | L-1 | Vol. 2 | 222 |
| 2. Property Controlling S T T in Section S T T S. Miscellaneous S T | R R R R | | | |
| Property in Sec. ST_ | R | <u>R</u> | tegister of Deeds Stamp | & File_Number |
| 4. Lot No, Recorded Plat | survey on <u>December 14</u> P. A. 74, Michigan P.A. of 19 In conformance with regulat f survey instructions of the flanagement or by a decree ded in lines 3, 4 and 5 ab an Board of Land Surve tablished, monumented, re II in the same town a therman Township, News | aygo County, Michigan. | 5 6 - 18 - 17 - 16 - 7 8 - 19 - 20 - 21 - 9 10 - 30 - 29 - 28 - 11 12 - 31 - 32 - 33 - 13 | 3 - 2 - 1 - 10 - 11 - 12 - 15 - 14 - 13 - 122 - 23 - 24 - 1 - 1 - 27 - 26 - 25 - 1 - 34 - 35 - 36 - 1 - 35 - 36 - |
| Robert A. Griffin R.L.S. #13584 LCRC #454 August 13, 1977 Searched for but did not find evidence of this corner. I then established this corner equal distance between the Northwest Corner and the Northeast Corner of Section 1 and on the township line. Set a 5" square X 36" concrete monument with brass cap. 24" White Oak S48°W 17.85' #1 4" X 7" Post South 32.93' #2 4" White Oak S07°W 75.41' #3 6" White Oak S29°W 59.61' #4 Concrete Monument East 0.62' (South One Quarter Corner, Section 36, T14N R13W)#5 | | | | |
| B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER: | | | | |
| Found 5" square concrete monument with brass cap. The centerline of the East and West dirt road is 3 feet \pm North. The condition of the recorded witnesses are: #1 thru #5 good condition. | | | | |
| C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER: | | | | |
| Accepted the 5" square concrete monument with brass cap as a substantial marker for the section corner and is accepted as the best available position for the location of this corner. | | | | |
| 36" White Oak (blazed) S53°W 17.91' Set spike with tag #22439 above old spike in Southeast side of tree. #1 4" X 7' Post South 32.93' #2 10" White Oak (blazed) S13°W 75.66' Found cabin spike in East side of tree. #3 14" White Oak (blazed) S36°W 59.66' Found cabin spike in West side of tree. #4 5" square concrete monument (South One Quarter Corner, Section 36, T14N R13W) East 0.62' #5 | | | | |
| Compadition | | | | |
| Norman L. Ochs Surveyor's Michigan License No. 224 Approved by Peer Review Group on Decem Norman L. Ochs, County Representative. | | | Der 18, 1998 Chigan State Board of Land Sur Re | veyors, Jan 28, 1971 evised May 14, 1975 Revised Jan., 1983 |