MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYOR COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

For corpore in

## LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 36

Newaygo (County)	Located in: Co	rner Code#	Line	am. Bun
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T <u>14N</u> R <u>14W</u> T R	(A3) V M-3	YOL. $oldsymbol{2}$	101
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous</li> </ol>	STR STR			
Property in Sec.	STR	R	Register of Deeds Stamp & Fil	e Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curro Department of the interior, Burea Law and/or that the corner poconformance with the rules of	_ , in a field survey on <u>November 6</u> , 19 ilrements of P. A. 74, Michigan P.A. of 1970, a above were in conformance with regulations ent manual of survey instructions of the United au of Land Management or by a decree of a ints mentioned in lines 3, 4 and 5 above the Michigan Board of Land Surveyors ished, re-established, monumented, re-more	the corner and rules ed States a Court of were in or by a	5	J K L M - 2 - 1 11 - 12 14 - 13 23 - 24 -
Note: Not more than 4 c recorded on this c	corners, all in the same town and ertificate.	range, may be	10 30 + 29 + 28 + 27 +	<del></del>
Northwest Corner, Section 7 Northeast Corner, Section 12	, Lincoln Township, Newaygo County, N 2, Denver Township, Newaygo County, I	<i>l</i> ichigan. Michigan.	12 31 + 32 + 33 + 34 +	35   36

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1838 Resurvey 12" Hemlock N26°E 27 Links (17.82')#1 28" Maple \$38°\_ 54 Links (35.64')#2

Sammy S. Barnett R.L.S. #16923 Recorded in Liber 348 Pages 4077-4080 September 19, 1988 Found 6" round concrete monument 12" Eim N05°E 25.85' #3 14" White Pine S63°E 22.40' #4 20" Maple S13°W 67.70' #5 14" White Pine S87°W 33.15' #6

George M. Blass R.L.S. #5489 LCRC #273 June 21, 1961 Located corner site from aerial photograph and government notes

Found remains of wood stake along side of corner fence post, fences East and South. Position of stake checks remains of government Hemlock witness tree Northwest. I placed a 6" diameter by 5 foot long reinforced concrete monument 18" above the ground at recovered corner point. 12" Elm N05°E 25.85 (scribed B.T. 6)#3 14" White Pine S63°E 22.40' (scribed B.T. 7)#4 20" Maple S13°W 67.70' (scribed B.T. 12)#5

14" White Pine S87°W 33.15' (scribed B.T. 12)#6

OVER &

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found George Blass 6" diameter concrete monument with brass cap, 10 inches above ground, on line with remains of fence running South and East. The woods line going South is 200 feet East. The corner is on extension of woods line going East. The condition of the recorded witnesses are: #1 thru #3 gone, #4 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 6" diameter concrete monument with brass cap as a substantial marker for the section corner and is accepted as a perpetuation of the original corner. Parties of the Partie

26" White Pine (blazed) \$55°E 22.4' Set spike and washer in	Northerly side of tree, #4	OF MICH.
24" Maple (blazed) S18°W 67.7' Set spike and washer in Wes	sterly side of tree, #5	
22" White Pine (blazed) S88°W 33.15' Set spike and washer	NORMAN	
20" White Pine blazed N12°W 25.58' Set spike and washer in	### LOCHS **	
$M = 0 \times 0$		* LAND *
Signed by toman of Ochs	Date November 10, 1997	SURVEYOR 6
Norman L. Ochs		22439
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of	Laft Surevers, Jan 28, 4974
		Revised May 14, 1955
		1983 <b>(1983)</b>
Approved by Peer Review Group on November 11, 1997  Norman L. Ochs. County Representative		Mariens John 1983

11.40