

MAR 02 1999

#### 1998 Newaygo County Remonumentation Project

# LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 40

SECTION

For corners in Newaygo (County)	Located in:	Corner Code #	Linda	M. Brow
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T R		vol. $oldsymbol{2}$	24
Property Controlling in Section     Miscellaneous Property in Sec.	TR STR STR STR		Register of Deeds Stamp & File	Number
4. Lot No, Records. Private Claims	rded Plat		1 A B C D E F G H I 2 - 6 + 5 + 4 + 3 1	J K L M
do hereby certify that under requipoints mentioned in lines 1 and 2 mentioned in the current bepartment of the Interior, Bured Law and/or that the corner polyconformance with the rules of	, in a field survey on Novem liferments of P. A. 74, Michigan P. above were in conformance with ent manual of survey instructions au of Land Management or by a nts mentioned in lines 3, 4 and the Michigan Board of Land ished, re-established, monument elow:	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	3 4	<del>         </del>
Note: Not more than 4 or recorded on this c	orners, all in the same to ertificate.	own and range, may be		1 1 1
Southeast Corner, Section 18	3, Lincoln Township, Newayge	o County, Michigan.	12 31 + 32 + 33 + 34 + 3	35 + 36 -

### A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye 1856 Resurvey 9" White Oak N40°E 18 Links (11.88')#1 6" White Oak S05°E 6 Links (3.96')#2

Delos G. Anderson (County Surveyor)
Book A, Page 205 June 17, 1897
Original Corner
Bearing trees standing.

Norman L. Ochs R.L.S. #22439

November 3, 1986 LCRC #798

Searched and did not find any evidence of corner, old witnesses or occupation. Treated this as a obliterated corner and set the corner by the proration of known later distances from nearest known corners. (½ Mile from the North, South and West and 1 mile from the East. Set a 30" long, 4" diameter Harrison cast iron monument marked "County Surveyor"

6" - 8" Clump of Maple S60°W 21. 78' #3

6" - 8" Clump of Maple S35°E 41.42' #4

13" Oak N75°E 47.74'

### B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

This was actually an obliterated corner and was set by proation of later distances. Found 4" diameter Harrison cast iron monument marked "County Surveyor" 4 inches ± above grade. The centerline of the North and South dirt road is 34 feet ± East and the remnants of the North and South fence is 20 feet ± West. There is no apparent East and West occupation. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good condition.

5" Oak N25°E 26.09' #6

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" diameter Harrison cast iron monument 30" long marked "County Survey" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

section corner and is accepted as a careful and faithful reesta	ablishment of the original corner.
4" - 12" Clump Maple (blazed) S85°W 21.73' Found spike with 6" - 8" Clump Maple (blazed) S23°E 41.37' Found spike with 16" White Oak (blazed) N85°E 47.75' Found spike with tag #28" White Oak (blazed) N50°E 26.13' Found spike with tag #2200 N50°E 26.13' Found spike with tag #2200 N50°E 26.13' Found spike with tag #2200 N50°E 26.13' Found spike with tag #200 N50°E 26.1	ag #22439 in Southwesterly side of tree. #4
Signed by Morman L. Ocho Norman L. Ocho	DateDecember 4, 1998
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on December 8, 1998 Norman I. Ochs, County Representation	Revised May 14, 1975 Revised Jan., 1983

11.80

