SUMMEY 8 REMONUMENT

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'97 FEB 12 PM 4 45

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74 Mich PA 1970

COMMISSIC	M LING VEGOIL	REWIEN I OF ACC 74, WICH. P.A	4. 1970 —	inda M	B	,
For corners in Newaygo (County)	Located in:	Corner Code #	O.	inda III	. Spocie	<i>,</i>
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T R T R T R	H-3	VOL. $oldsymbol{2}$	PAGE	15	
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		ster of Deeds_St	amp & File <i>l</i>	Number	
				OEFG		
	rded Plat		ï-ĭ-ř		- <u> </u>	-\-
5. Private Claims			2 - 6	-5- 4 -		_ _
			3	- -	_	_ _
I Norman I Oche	in a field supply on December	r12 10 08	4 }	_ _ _ _	-10	
I. Norman L. Ochs , in a field survey on <u>December 12</u> , 19 96 , do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner			s l		-,,,,,	-12-
points mentioned in lines 1 and 2			_ _ _ -	_ _		
	ent manual of survey instructions		° 18	-1718	-13	i 3
Department of the Interior, Bureau of Land Management or by a decree of a Court of			7} -		- -	
Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a			8 10	-2021	-22	21-
Decree of a Court of Law; estab	0	_	_ _ _ _	[_		
recovered, found as expressed by	pelow:		10	-20	-2728	
			11		-27	-25
Note: Not more than 4 corners, all in the same town and range, may be			13	_ - - - -	- -	_ _
recorded on this	certificate.	_	'^ 31 -	-3233	-31 35 -	—₫g
	·	wnship, Newaygo County, Mic			<u> </u>	!
A. DESCRIPTION OF C	RIGINAL MONUMENT A	AND ACCESSORIES AND/OF	COURSECTOEN	I KESTOR	ATION:	
G.L.O. Milton Nye Resurvey 6" White Pine N10°E 21 Link 15" White Pine S14°W 15 Li	ks (13.86')#1		,			

Robert A. Griffin R.L.S. #13584 LCRC #66 September 21, 1970

Found the stump of one original bearing tree. From this remaining witness I measured recorded distance and bearing (N14°E 9.24') to a point which is proper location of the One Quarter Corner. Set a 5" Square reinforced concrete monument with brass disk.

6" - 6" Twin White Oak S23°E 44.38' #4

4" X 7' Treated Post South 1.55' #5

5" Red Oak S73°W 101.32' #6

8" White Oak N42°W 67.86' #7

4" White Oak N06°W 57.72' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR **REESTABLISHING CORNER:**

Found Robert A. Griffin's concrete monument with brass cap cracked 1 foot below ground. Placed cardboard box around cracked base and filled with concrete to a below ground depth of 18 inches to stablize the monument. The centerline of East and West trail road is 9 feet North and East and West fence line is 27 feet North and the fence line going West is 9 feet South. The condition of the recorded witnesses are: #1 gone, #2 thru #4 good condition, #5 gone, #6 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted Robert A. Griffin's concrete monument with brass cap as a substantial marker for the section corner and is accepted as a careful and faithful perpetuation of the original corner. MICHIO,

15" Pine Stump S13°W 9.2' (center) #2	
East edge of marsh N86°W 383'± #3	
12"-10" Twin White Oak S23°E 44.38' Spike in West side of tre. #4	
12" Black Oak \$75°W 101.32' Spike in Southeast side of tree, #6	
14"-6" Twin White Oak N36°W 68.05' Spike in Northeast side of tre	e. #7
6" White Oak N06° W 57.72' Spike in West side of tree. #8	•
Signed by Amon T. Ochs	Da

22439

December 20, 1996

PED LAND Form approved by Michigan State Board of Land Su

Revised May 14, 1975

NORMAN L. OCHS LAND SURVEYOR

22439

Revised Jan., 1983

Norman L. Ochs, County Representative.

Norman L. Ochs

Approved by Peer Review Group On December 23, 1996

Surveyor's Michigan License No.