NEWAYGO COUNTY REGISTER OF DEEDS

MAR 1 3 2000

1999 Newaygo County Remonumentation Project DA. M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATEEB 28 PM 1 17

For corners in Newaygo (County)	Located in:	Corner Code #	Linds M. B.	oww.
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T R T R T R	<u>l-7</u>	$^{'}$ vol. $oldsymbol{2}$	35
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp 8	
coints mentioned in lines 1 and 2 coints mentioned in lines 1 and 2 herefore as required in the curre Department of the Interior, Burea aw and/or that the corner poir conformance with the rules of	, in a field survey on <u>December</u> rements of P. A. 74, Michigan P. A above were in conformance with rint manual of survey instructions of u of Land Management or by a hits mentioned in lines 3, 4 and the Michigan Board of Land shed, re-established, monument	er 1 , 19 90 , A. of 1970, the corner regulations and rules of the United States decree of a Court of I 5 above were in Surveyors or by a	A B C D E F G 2 - 6 - 5 - 4 - 4 - 7 - 8 - 9 - 1 5 - 18 - 17 - 16 - 1 7 - 16 - 1	H I J K L M 3 - 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Note: Not more than 4 corecorded on this co	orners, all in the same to ertificate.	wn and range, may be	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	7 - 26 - 25 -
Southeast Corner, Section 15	, Lincoln Township, Newaygo	County, Michigan.	$\begin{array}{c} 12 - 31 + 32 + 33 + 3 \\ 13 \end{array}$	4 + 35 + 36 -
A. DESCRIPTION OF OR	IGINAL MONLIMENT AND	ACCESSODIES ANDA	OD CLIDOFOLIENT DEST	

ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 14" Beech N71°E 26 Links (17.16')#1 24" White Pine S57°W 29 Links (19.14')#2

Newaygo County Road Commission Sheet Railroad Rail 1956 24" Black Oak N41°W 51.2' #3 24" White Oak N32°E 37.4' #4 16" Beech S12°W 71.7' #5

Robert A. Griffin R.L.S. #13584 1978

Found Iron in center of East and West pavement (did not dig up)

2" Pipe Street Sign S27°W 25.4' #6

Red Oak N40°W 52.7' #3

Norman L. Ochs R.L.S. #22439 January 22, 1985 **Drawing Number 85135B** July 23, 1986 Drawing Number 86146B Set P.K. nail (1985) Found P.K. nail (1986) 24" Black Oak N41°W 51.20' #3 24" White Oak N32°E 37.40' #4 16" Beech S12°W 71.70' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Railroad Rail raised with a ½" x 14" Rod, raised with 5/8" x 16" rod, raised with P.K. nail and the centerline of the East and West bituminous road is 1.5 feet ± South and the centerline of the two-track going North is 4 feet ± West. There is no apparent occupation going South. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #5 good condition, #6 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed P.K. nail and 5/8" x 16" Rod and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" over 1/2" x 14" Rod and Railroad Rail as a substantial marker f faithful

reestablishment of the position of the original corner.	er for the section corner and is accepted as a careful and fai
48" Red Oak N40°W 52.7' (has B/T tag) Set spike with tag #40" White Oak N30°E 38.39' Set spike with tag #22439 in W 18" - 22" Twin Beech S10°W 72.27' Set spike with tag #2246" Red Oak S15°E 70.29' Set spike with tag #22439 in West	Vest side of tree. (3' ± above grade)#4 39 in West side of tree, #5
Signed by 10 man L. Ochs Norman L. Ochs	Date December 10, 1999
Surveyor's Michigan License No. 22439	Form approved by Michigan State Based of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on	Revised May 14, 1975 Revised Jan., 1983

NORMAN L. OCHS 22439