

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS

LINDA M. BROWN

MAR 0 2 1993

LAND CORNER RECORDATION CERTIFICATE '99 FEB 17 PM 3 11 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

4. Lot No, Recorded Plat	
4. Lot No, Recorded Plat	
4. Lot No, Recorded Plat	Deeds_Stamp & File_Number
5. Private Claims 2 - 6 - 3 - 6 - 1. Norman L. Ochs, in a field survey on	2 D E F G H I J K L M - 5 - 4 - 3 - 2 - 1 - 1 - 8 - 9 - 10 - 11 - 12 - 1 - 17 - 16 - 15 - 14 - 13 - 1 - 20 - 21 - 22 - 23 - 24 - 1 - 29 - 28 - 27 - 26 - 25 - 1 - 32 - 33 - 34 - 35 - 36 - 1

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1838 12" White Oak for Quarter Section Corner

Lyle S. Shepherd R.L.S. #503 Book 32, Page 32 and 33 October 27, 1926 Stone Pine Stump N56°W 181/2 Links (12.21')#1 Pine Stump \$32°W 131/2 Links (8,91')#2

Robert A. Griffin R.L.S. #13584

LCRC #328 June 19, 1974 Did not find a monument at this corner. I then placed a 10" dock spike equal distance and on a straight line between the Southwest Corner and the Southeast Corner of Section 35. Replaced with a 5" X 36" concrete monument. Power Pole N79°E 139.35' #3

North One Quarter Corner, Section 2, T13N R13W, N89°21'30"E 18.15' #4

4" Red Oak N61°W 128.44' #5

Norman L. Ochs R.L.S. #22439 June 4, 1984 Drawing Number 84073B Found concrete monument. Power Pole N79°E 139.30' #3 North One Quarter Corner, Section 2, T13N R13W, East 18.49' #4 4" Red Pine N61°W 128.49' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 5" square concrete monument. The centerline of the East and West dirt road is 2 feet ± South. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #5 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACTHE POSITION OF THE CORNER:	CCESSORIES ESTABLISHED TO PERI	PETUATE LOCATING
Accepted 5" square X 36" concrete monument as a substantial faithful reestablishment of the original corner.	marker for the section corner and is acc	epted as a careful and
Power Pole N83°E 139.25' Found spike with tag #13584 in N 5" square concrete monument (North One Quarter Corner, S 12" Red Pine (blazed) N55°W 128.43' Found cabin spike in N 10" Juniper N10°E 125.37' Found spike with tag #22439 in Ea 10" - 10" Twin White Oak (blazed) S21°E 118.23' Found spike Signed by Norman L. Ochs	Section 2, T13N R13W) East 18.49' #4 Northeast side of tree. #5 ast side of tree.	NORMAN L- OCHS LAND SURVEYOR 22439
Surveyor's Michigan License No. 22439 Approved by Peer Review Group on December 22, 1998 Norman L.,Ochs, County Representative.	Form approved by Michigan State Board of Land 8	