LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

VOL 001 PAGE 119

For corners in .				
Newaygo (County)	Located In:	Corner Code ##	NEWAYGO	
Public Land Survey	T 14N R 11W	. C-7·	REGISTER C	
	T R			
	T R T R		'95 MAR 14	PM 3 57
2. Property Controlling	S R			-D 0
in Section 3. Miscellaneous	S T R S T R		Marlena. Register of Deeds Stan	/00g004
Property in Sec.	S T R		Register of Deeds Stan	np & rie Number
4. Lot No	, Recorded Plat		A B C D E	FGHIJKLM
5. Private Claims			2 6 5 5	3 2 1
	•		3	
Norman I Oo	the Octob	per 15	94	10 11-12
do hereby certify that under	ths, in a field survey on Octob requirements of P.A. 74, Michigan P.A.	of 1970, the corner points me	ntioned 6 1 1	
in lines 1 and 2 above we	re in conformance with regulations ar instructions of the United States Depar	nd rules therefore as required	in the []	
Management or by a decree	e of a Court of Law and/or that the corne	er points mentioned in lines 3,	4 and 5 8 19 20 2	1-22-23-24-
Court of Law; establishe	e with the rules of the Michigan Board od, re-established, monumented, re-	monumented, recovered, fo	und as 9	
expressed below:	A all in the same town a	nd range may be recorde	90 120	8 27 26 25
on this certifica	4 corners, all in the same town a ate.		12 31 32 3	3-34-35-36
NE Corner, Sec.	19, Goodwell Twp.,	Newaygo County	MI 13	
A. Description of origin GLO John Hodgso	nal monument and accessories an on 1837	d/or subsequent restoration Wm. M. Jacques	on: NCRC Sheet	
8" Birch S55°E	23 1ks (15.81')#1	(County Survey	or) Iron	COST 100 21 JL/
	W 38 1ks (25.08')#2	Book 24, Pg. 8 June 18, 1903	P.Pole S36	660°W 109.2 ' #4 °W 56.5' #3
Delos G. Anders Book A Pg's 221	son (Co. Surveyor)	Measured 79.80	chains 8" W. Oak	N37°W 55.6' #5
No timer or stu	ımp near.	(5266.80 ft.) NE cor. to the		
Measured (40.00) chains) 2640 ft.	Sec 19	: NW COI. OI	-OVE <u>R</u>
from the N-1/4 19. measured 40	cor. to NE cor., Sec 0.06 chains (2643.96	:. ft.)		
from the NW con).06 chains (2643.96 to N-1/4 cor. of Se er evidence found and/or method	ec. 20 applied in restoring or ree	stablishing corner:	
	that had been raised			vel road is
3 feet north of	corner. Fnd glass	around rod also).	
Condition of ol	ld witnesses are 1 th 2.2', No. 5 thru 7 am	nru 3 gone, No. re good. We mea	4 is a rotted stum sured 5266.71 ft.	ip, distance to to the NW corne
f Sec. 19 and 2	2632.69 to the N-1/4	cor. of Section	19.	
C Description of monu	ument for corner and accessories	established to perpetuate	locating the position of the co	rner:
	l and 1" iron pipe a			
ong for a subst	antial marker for th	he section corne	er and is accepted	as a careful
nd faithful ree	establishment of the & 17" N37°W 55.58' S	original corner	. 165	#ICU
6" B. Oak N77°E	E 112.70' Spk. on S :	side #7.	A CONTRACTOR OF THE PARTY OF TH	
.P. S60°W 94.89	ال Spk. on North side	e #6	22 π ε .	RMAN XXXX
W. Oak 541 E	32.61' Spk. on SWly	side.	∄★	edb Viyor }
				730 /3 j
./	1000		2	Commence of the state of the st
Marine	m L Ocha	Date	October 18, 199	AND
Signed by Norman	L. Ochs 22439			and the companies part as above
Surveyor's Michigan Lic Approved by Pee	er Review Group on Oc	tober 19	1994.	D OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983
Norman L. Ochs,	, County Representati	rve		HEA1950 TWW" 1282
n. L. O.		· Marine	•	; -
\$ 9.00 (4.00)	SURVEY &			
√	REMONIUMENTATIO	NI Java	:	*
	1 80 20 1 21 31 325 5 1 V 8 5 T LV 1 64 1 H	FINE SERVICES OF THE SERVICES		1

JEC 07 2000

RECTION

. cont.

Nugust 7, 1981 N.E. & S. Co. Found 5/8" rod raised w/1" pipe L4"-14" Tw. W. Oak N37°W 55.6' #5?.Pole S60°+W 94.86'
20" P. Stp. CL S60°W 109.2' #4 24" B. Oak N65°+E 112.79' #7

Measured 2637.67 ft. from the NW Cor. to N-1/4 cor. of Sec. 20 and measured 2618.50 ft. from the NW cor. to the W-1/4 cor. of Sec. 20.

1984 Patrick Leemon Iron 18" Pine S60°W 109.2' #4 P.P. S36°W 56.5' #3 Tw. Oak N37°W 55.6' #5

Measured 2637.56 ft. from the NW cor. to the N-1/4 cor of Sec. 20 and measured 2618.46 ft. from the NW cor. to the W-1/4 cor. of Sec. 20

SURVEY & REMONUMENTATION

DEC ♥ 7 2000

PECTION