SURVEY & REMONUMENTATION

1995 Newaygo County Remonumentation Project

APR 0 4 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 **VOL. 1**

PAGE

NEWAYOU COUNTY

Marlone Toones

For corners in Newaygo Located in: Corner Code # MARLEY (County) 198 FIB 21 - AM -9 -41 1. Public Land Survey T 14N R 11W G-9 2. Property Controlling in Section S R 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number

l, Norman L. Ochs , in a field survey on September 9 , 19 95 do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented,

recovered, found as expressed below:


4. Lot No.

5. Private Claims

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

S.W. Comer, Section 22, Goodwell Twp., Newaygo Co., Mi

, Recorded Plat



A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J. H. Mullett 1837 8" Maple N56°E 30Lks (19.80')#1 10" Beech S68°W 76Lks (50.16')#2

William M. Jacques (Co. Surveyor) Book 8 Pg. 75 1904 Measured 80 ch 53 ft (5333 ft) from the N.E. Cor. to the S.E. Cor. of Sec. 21

Robert A. Griffin RLS #13584 LCRC #451 October 31, 1977 Found 11/2"x32" strap iron by Shepherd in nest of stones Replaced with 5"x60" Conc. Mon. with brass cap P. Pole N52°E 60.10' #6 5"-6" Tw. Maple N68°W 18.86' #7 5" Maple S05°W 53.22' #8 4"x4" Post South 1.0' #9 Measured 2619.48 ft from the N.W. Cor. to the N 1/2 Cor. of Sec. 27

William M. Jacques (Co. Surveyor) Book 8 Pg. 36 Dec. 20, 1905 Measured 79.50 ch (5247 ft) from the N.E. Cor. to the S.E. Cor. of Sec.

Lyle S. Shepherd RLS #503 Book B Pg's 86 & 87, Witness Book No. 1 Pg. 6 Book 70A Pg's 3-5 May 2, 1934 Iron and pine stake 20" Pine Stp. N80°W 37.5' #3 20" Pine Stp. N371/2°E 71.3' #4 18" Pine Stp. S271/2°W 24.8' #5 Measured 2595.2 ft from the S.E. Cor. to the S 1/4 Cor. of Sec. 21 and Measured 2652 ft from the S.E. Cor. to the E 1/4 Cor. of Sec. 21

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING

Found R.A.G. monument with brass cap at apparent P.I. of curve and the centerline of road going North is 45 ft East and measured 2651.29 ft from the W ¼ Cor. to the S.W. Cor. of Sec. 22 and the condition of the recorded witnesses are: #1 thru #5 gone, #6 thru #8 good condition, #9 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted R.A.G. monument with brass cap as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

P. Pole N52°E 60.11' Spike in Southeast side of pole. #6 12" Tw. Maple N68°E 18.84' Spike in Southwest side of tree. #7 10" Maple S05°W 53.22' Spike in East side of tree. #8 8" Maple S40°E 8.63' Spike in North side of tree

chs 1 10 man Signed by_ Date September 11, 1995 Norman L. Ochs

Surveyor's Michigan License No.

Approved by Peer Review Group On October 3, 1995

Norman L. Ochs, County Representative.

M. L.O.

CORNER:

OI MICHIE Revised May 14, 1975 Form approved by Michigan

NORMAN

L OCHS LAND SURVEYOR 22439

Revised May 14, 1975 Revised Jan., 1983