MAY 28 1997

1996 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYCOCOUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION	FILING REQUI	REMENT of Act 74, Mich. P	P.A. 1970	LI	NDA M. I	BROWN	
For corners in Newaygo	Located in:	Corner Code#		'97 FE	B 12	PM 4 L	45
(County)		Cumer Code #		J.	מציגונה או	. Brow	א ענ
Public Land Survey	T <u>14N</u> R <u>11W</u> T R T R	K-3		Spar.	de 111	·	~~~
2. Property Controlling sin Section s	TR STR STR_		VOL.	1	PAGE	249	9
3. Miscellaneous S Property in Sec. S	ST R ST R		ister of Dee	ds_Stam	ıp & File	Number	_
4. Lot No, Recorder 5. Private Claims	d Plat					å	
		•	Λ <u>η</u>	COE	F G II	JK	L M
I, <u>Norman L. Ochs</u> , in a do hereby certify that under requirem	a field survey on September	11 19 96	?	-			_
points mentioned in lines 1 and 2 abo	OVe Were in conformance with	regulations and rules	3	<del></del>   -	-  -	-	-
ulerelore as required. In the current manual of survey instructions, of the United States.				·	-9 10-		2
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in				-11-	-   -	-	
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented,				·[ -	-1616	- - -	3-
recovered, found as expressed below	ed, re-established, monument v	ed, re-monumented,	7	╏┈╏┷╏╸	-   -	- - -	
			8 19	-20	-21	-   2 3   3	24
Note: Not more than 4 corners, all in the same town and range, may be			P	·  -	- - - -	- - -	
recorded on this cer	tificate.		10 -30-	-29	-2027-	26 :	5-

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

Southwest Comer, Section 1, Goodwell Township, Newaygo County, Michigan

G.L.O. J.H. Mullett 1837 6" Beech S22°W 28 Links (18.48')#1 14" Black Oak S77°E 29 Links (19.14')#2

William M. Jacques (County Surveyor) Book B Page's 38 & 39 and Book 39 Page's 15-17 April 24, 1909 Stake with broken glass

Douglas Perry P.E. #19302 June 1, 1972 NCRC Found 1/2" Rerod Axle Shaft North 65.50' #6 Axle Shaft South 174.40' #7 Wooden Stake 15' East of (Guard Stake)#8

William G. Tingley R.L.S. #30104 April 10, 1989 Found 1/2" Pipe Power Pole North 35,25' #9 18" Poplar S60°E 65.40' #10 Northeast Corner House S56°W 126.10'#3

Lyle S. Shepherd R.L.S. #503 Book 36 Page 94 and Book B Page's 78 &79 July 27, 1914 Well Point Northeast Corner House Wall S54°10'W 1.91 Chains (126.06')#3

NCRC Sheet Iron Power Pole N26°E 74.3' #4 Northeast Corner House S56°W 126.10#3 18" White Oak S60°W 80.5#5

John Milletics R.L.S. #25859 December 5, 1981 Project Number 81-080 Found 3/1 Pipe Power Pole North 35.25' #9 30" Oak S50°W 81.55' #5 18" Poplar S60°E 65.40' #10

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 3/2" pipe in fence line to North and the centerline of the road going South is 1.5 feet East and the centerline of the East and West road is 1 feet North and the condition of the recorded witnesses are: #1 and #2 gone, #3 thru #7 good condition, #8 and #9 gone, #10 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed %" pipe and set 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Northeast Corner House S56°W 126.10' #3
Power Pole N26°E 74.3' Found tag #5489 on note #4
28" White Oak S60°W 81.44' Spike in Northwest side of tree. #5
Axle Shaft North 65,50' #6
Axle Shaft South 174,40' #7
18" Poplar S60°E 65/40' Nail in Northeast side of tree. #10
Signed by Iloman L. Ocho.
Norman L Ocho

22439

Date September 13, 1996

PED LAND Form approved by Michigan State Board of Land Sul

Revised May 14, 1975 Revised Jan., 1983

BICHICA

ijŧ

NORMAN L. OCHS LAND SURVEYOR

22439

Approved by Peer Review Group On October 24, 1996 Norman L. Ochs, County Representative. M. L.O

Surveyor's Michigan License No.