

1996 Newaygo County Remonumentation Project

MAY 28 1997

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

For corners in Newaygo	Located in:	Corner Code#		97 FEB 12	·
(County) 1. Public Land Survey	T <u>14N</u> R <u>12W</u> T R	B-13	(Linda M). Brown
Property Controlling in Section Miscellaneous	TR TR STR STR STR		VOL. 2	PAGE	4
Property in Sec.	STR	Regis	ter of Deeds. S	tamp & File Nu	ımber
do hereby certify that under req points mentioned in lines 1 and 1 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po conformance with the rules of	, in a field survey on October 2 uirements of P. A. 74, Michigan P. 2 above were in conformance with rent manual of survey instructions au of Land Management or by a bints mentioned in lines 3, 4 and the Michigan Board of Land blished, re-established, monument	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	7 - 19 - 19 - 19 - 19 - 19 - 19 - 19 - 1		19 J K t, M 3 2 1- 1- 12- 1 19 11 13- 1 15 14 13- 1 22 23 24- 1
Note: Not more than 4 recorded on this	corners, all in the same certificate.	town and range, may be	11		21 — 25 — 25 — 31 — 35 — 38 —
South One Quarter Com	er, Section 31, City of Whi	te Cloud, Newaygo County, M	ichigan		
A. DESCRIPTION OF C	DRIGINAL MONUMENT A	ND ACCESSORIES AND/OR	SUBSEQUE	NT RESTORA	TION:
G.L.O. John Hodgson 1838	3	Ralph A Smith R I S #342	1 1958		

G.L.O. John Hodgson 1838 8" Black Oak N55°W 17 Links (11.22')#1 7" Pine N11°E 36 Links (23.76')#2

Ralph A. Smith R.L.S. #3421 1958 North One Quarter Corner, Section 6, T13N R12W, (%" Gas Pipe) is West 9.57" #3

Newaygo Engineering and Survey Company
July 30, 1990 Set ½" Rod and cap #22439
North One Quarter Corner, Section 6, Everett Township West 9.57' #3
12" Black Oak S80°W 2.98' #4
14" White Oak S10°W 33.10' #5
14" Twin Black Oak North 31.64' #6
10" Black Oak N80°E 13.48' #7

Newaygo Engineering and Survey Company
October 4, 1994 Found ½" Rod and cap #22439 LCRC #1232
North One Quarter Corner, ¾" Iron Pipe, Section 6, Everett Township West 9.53' #3
Concrete Corner Fence Post S05°W (tree in way) #8
14" Red Oak S80°W 2.98' #4
14" White Oak S10°W 33.07' #5
14"-14" Twin Black Oak North 31.39' #6
10" Black Oak N80°E 13.39' #7

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" Rod and cap #22439 and the centerline of gravel road going West is 7 feet South. The centerline of gravel road going South is 35 feet West and fence going South is 10 feet West and the condition of the recorded witnesses ar: #1 and #2 gone, #3 thru #7 good condition, #8 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ½" Rod and cap #22439 and set a 4" diameter Harrison of marker for the section corner and is accepted as a careful and faithful	ast iron m Il reestablis	onument 20" long marked shment of the original con	d "County Surveyor" as a substantial ner.
North One Quarter Corner, Section 6, T13N R12W, West 9.57' (%" 14" Black Oak S80°W 2.98' Spike in North side of tree. #4 18" White Oak S17°W 33.04' Spike in West side of tree. #5 16"-14" Twin Black Oak North 31.71' Found nail in West side of tree. 12" Black Oak N80°E 13.39' Spike in North side of tree. #7 34" Black Oak N45°W 35.88' Found spike in Southwest side of tree. 22" White Oak S62°W 72.1' Set spike and tag over existing nail.	.#6	#3 October 22, 1996	NORMAN L. OCHS LAND SURVEYOR 22439
Norman L. Ochs		October 22, 1990	TAND
	Form appro	oved by Michigan State Board	of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group On October 24, 1996			Revised May 14, 1975
Norman L. Ochs, County Representative.			Revised Jan., 1983
M 4 B	-	•	• .