MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

( NEXPERIENCE	TICINO REGO	PIREMIENT OF ACT 74, Mich. F	P.A. 1970 🛂 ດາ	FEB 12 F	om 11 111
For corners in			31	LED TS L	77 7 7
_Newaygo					
(County)	Located in:	Comer Code #		0.	A
(Oddrity)			Ċ	linda M.	Diama
1. Public Land Survey	T <u>14N</u> R <u>12W</u> T <u>13</u> NR <u>12W</u> T R	E-I	_	,	
<b>^</b>	TR		VOL. $oldsymbol{2}$	PAGE	6
2. Property Controlling S	TR				•
in Section S	TR	<del></del>			
3. Miscellaneous S	TR	<u> </u>			
Property in Sec. S	TR	Pan	ictor of Danie of	<b></b>	_
4 1 -4 11	, - <del>-</del>		ister of Deeds Sta	ımp & File Nur	<u>nber</u>
4. Lot No, Recorded 5. Private Claims	Plat				
		· · · · · · · · · · · · · · · · · · ·	Λυςυ μ		_
•					KLM
Norman L. Ochs in a t	field survey on October	2 40.00	2 - 6 - 1 - 5 - 1		1111
The stay certify that linder requirem	onte of D. A. 74 Minhimon M		- al   i		[- -
			<u> </u>		lll
			1	-9-1-10-1-1	1_[_/ <sub>2</sub> ]
			5	111	<u>                                     </u>
				_ _ _ _	<b>]</b>
			0 -10-17-17-1	-1'6	1-1-13-
conformance with the rules of the Michigan Board of Land Surveyors or by a  Decree of a Court of Law; established, re-established, monumented, re-monumented,					
recovered, found as expressed below:	,	······································		_ _ _ _	- - -
Notes Not many the s			-19	-21222	3
Note: Not more than 4 corners, all in the same town and range, may be			_ _ _ _		
recorded on this certi	ificate.	, , , , , , , , , , , , , , , , , , ,	. 10		
		•	,,	-20272	
Southwest Corner, Section 33	3. City of White Cloud	I Noumanno Onemet Batter	· ''/ <del></del>     -	~ <b>!~!~!~!</b>	
Northwest Corner,	Section 4, Ci	ty of White Claud	12 -3 32	-3331 31	536
A. DESCRIPTION OF ORIGI	INAL MONHMENT A	Newaygo County, 'N	1I 13 L		
Southwest Corner, Section 33 Northwest Corner, A. DESCRIPTION OF ORIGI	WAL MONORISM A	IND ACCESSORIES AND/OF	RSUBSEQUENT	RESTORATION	ON:
G.L.O. John Hodgson 1838				– • • •	. • •
14" Hemlock N63°E 45 Links (29.	<b>プ</b> ^#1	Lyle S. Shepherd R.L.S. #	503 1916		
12" Pine N55°W 30 Links (19.8')#2		Book 47 Page 90			
11 00 Links (15,0 jm.	2	Black Oak Southwest 73.2	<b>#</b> 3		
William M. Jacques (County Surve	ume)	Black Oak Northeast 59.31;	#4	-	
Book B Page's 10 and 11 Novemi	<i>yui)</i>	White Oak Northwest 85.4	#5		
Book 10 Page 18	Der 4, 1904	4.			
Found the old corner and the control	to a s	Lyle S. Shepherd R.L.S. #5	03		
Found the old corner-set new stake with brick around the post		"Supervisor's Plat No. 1 Wil	COY" recorded in Lib	ar 2 af DI-1-	
are bost		Page 63 June 2, 1930, No	theset Corner of -1-	ei o oi Piais,	
		Set normanantt-1	ranger country bis	IC.	

Patrick A. Salisbury R.L.S. #13594 Drawing Number 73072B July 11, 1973 Found 1" Pipe

NCRC Sheet 1" Pipe Power Pole \$40°W 71.0' #9 2" Pine S45°E 106.0' #10

ent metal monument not less than one inch in diameter and 15 inches in length set in a concrete base at least 4 inches in diameter and 48 inches in depth.

Ralph A. Smith R.L.S. #3421 1953 Field Book 68 Page's 72 and 73 Field Book 71 Page's 170 and 171 Found 1" Gas Pipe

Newaygo Engineering and Survey Company October 26, 1982 Found %" Pipe Street light and Power Pole North 27.16' #6 Power Pole S40°E 49.59' #7 Power Pole S40°W 52.93' #8

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" Pipe in concrete monument in the centerline of the East and West road extended and the centerline of the road going North is 35 feet West and the condition of the recorded witnesses are: #1 thru #5 gone, #6 thru #8 good condition, #9 and #10 gone. This Pipe is

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 3/4" Pipe in concrete monument as a substantial marker for the section corner and is accepted as a careful and faithful

resemblishment of the original comer.	and an area production and the	a careiar and railing	
Stop light and Power Pole North 27.37' Spike in East side of pole. #Power Pole S40°E 49.44' Spike in West side of pole. #7 Power Pole S40°W 52.93' Spike in West side of pole. #8 15" White Oak S80°W 73.09' Set spike and tag in North side of tree Signed by  Norman L. Ochs		NORMAN L. OCHS LAND SURVEYOR	****
Surveyor's Michigan License No. <u>22439</u>	Form approved by Michigan State Board of L	22439	
Approved by Peer Review Group On October 24, 1996  Norman L. Ochs, County Representative.		Revised MIP14 4	75 83