MARLENE TOOGOOD

MARKARIONI.	. 91	LAND
COMMISSIO		Filing

CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ment of Act 74, Mich. P	.A. 19764 JAN 21 P	77 3 21
Newaygo			6	-D 1
(County)	Located In:	Corner Code ##	Marlena	1009004
Public Land Survey	T 14N R 14W T R	A-2	vol. 001	PAGE 36
2. Property Controlling	T R T R S T R			
in Section 3. Miscellaneous	S T R S T , R			
Property in Sec.	S T R	414,	Register of Deeds S	tamp & File Number
	lecorded Plat		A B C D	EFGHIJKL
5. Private Claims			2 6 5 5	4 3 2 1 -
			3	
, Norman L. Ochs	, in a field survey on Decembe	r 17 . 93	4 - 7 - 8 -	9-10-11-12-
do hereby certify that under red in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with Court of Law; established, rexpressed below:	purements of P.A. 74, Michigan P.A. on conformance with regulations and actions of the United States Departmation of Law and/or that the corner the the rules of the Michigan Board of e-established, monumented, re-materials.	f 1970, the corner points ment rules therefore as required intent of the Interior, Bureau of points mentioned in lines 3, 4 Land Surveyors or by a Decreponumented, recovered, four	n the Land 7 and 5 8 19 20 e of a 9	
	orners, all in the same town and		12 31 32	-33 -34 -35 -36
	Section 6, Denver Towns		13	
A. Description of original r	monument and accessories and/	or subsequent restoration	:	
	ks. Government Surv (No accessories aug. 28, L.S. P.A.S. 13 found 3/4" x 1 rvey N82W Power Pole	d corner of ey. given). 594, 1973 8" iron pipe e g House e pplied in restoring or reest	ablishing corner:	Subdivision shows corner t NE corner of ent is 33' to Wes
	: ::			
-			* * 10.00	NORMAN L. OCHS SULVEYOR 22439 20 IAND
C Description of monumer	nt for corner and accessories es	tablished to perpetuate lo	cating the position of the	corner:
Set a 4 ¹¹ Harrison C	ast Iron Marker as a su l and faithful re-estal	ıbstantial marker f	or the Section cor	ner, and is
4" Cast Iron Marker AZ 59° 11" Elm Stump AZ 90° 3/4" OD Pipe AZ 266° Power Pole AZ 329° SE Cor Log H	NIR 107.20' 32.99' 33.10'		,	
_	vertically into expos	ed tree root. Azii	muths are shown abo	ve.
9/	La I	7	December 27, 1993	
Signed by Norman L. Och Surveyor's Michigan License Approved by Peer Rev Norman L. Ochs, Cour	riew Group on December 1	Date	FORM APPROVED BY MICHIGAN STATE BO	ARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 198

A. cont.

L.S. J. E. Evans 22431 June 9, 1980, Unrecorded survey found in Oceana County Circuit Court 79-1706-CH, found steel rod.

East 20" Oak 20' SW 20" Oak 49'

33.0' L.S. N. Ochs 22439, January 15 1988 Found 3/4" pipe N10°E Maple 150.55' S82°W Power Pole 33.10' East 1/4" rod 32.97' N35°W SE Cor. Log Hse 120.90'

LS, W. Fries, Jr., May 23, 1988. Fnd. 1" iron, 4' West of the occupied centerline of a North-South road & in occupation to West. Recorded Corner Form 911

AZ 59 11" Elm NIR 107.20' AZ 90 3/4" Pipe 32.99' AZ 270 Conc. mon. 32.67' AZ 329 SE Cor. Log Hse 120.73'