

MAY 28 1397

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code #	C	Linda V	n. Brozon
1. Public Land Survey	T <u>15N</u> R <u>12W</u> T R T R	D-7	uoi S	B. 4.5	9.0
Property Controlling in Section Miscellaneous	T R S T R S T R	•	VOL. 2	PAGE	26
Property in Sec.	S T R				
r roporty in Oec.	S / K	Reg	ister of Deeds Sta	pp & File N	umber
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the currel Department of the Interior, Bureal Law and/or that the corner point conformance with the rules of Decree of a Court of Law; establisticovered, found as expressed be	n a field survey on	A. of 1970, the corner egulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a ed, re-monumented,	2		
Note: Not more than 4 c recorded on this c	orners, all in the same to ertificate.	own and range, may be	12		-3536
North One Quarter Corner	Section 20 Monroe Tow	nshin Newayaa County Mi	ahiman	•	

ion 20, Monroe Township, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856 8" Maple N69°W 17 Links (11.22')#1 24" White Pine S66°E 39 Links (25,74')#2

Jack E. Pierson R.L.S. #19305 May 1, 1982 Found Forest Service Monument Recorded in Series M Number 7436 8"-10" Clump Maple N30°W 33.50' #3 14" Black Oak \$50°W 35,32' #5 16" Red Pine S72°E 80.53' #6

Patrick A. Salisbury R.L.S. #13594 1972 Set 5" X 5" X 3' Concrete Monument with brass cap 8"-10" Clump Maple N30°W 33,50' #3 Forestry Post West 8.5' #4 14" Black Oak S50°W 35.32' #5 16" Red Pine S72°E 80.53' #6

William Fries Jr. R.L..S. #30389 LCRC #879 May 5, 1988 Found Forest Service Monument on the West Edge of a North and South road. Raised with a ½" Iron and cap. 12" Poplar N59°E 68.90' #7 20" Red Pine S74°E 80.50' #6 20" Black Oak S49°W 35.26' #5 21" Oak N88°W 69.40' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found William Fries 1/2" Rod and Cap over Concrete Monument with brass cap. Concrete Monument is 25" below the ground and the centerline of North and South road is 12 feet East and on line with fence line going West and the condition of the recorded witnesses are: #1 thru #4 gone, #5 and #6 good condition, #7 gone, #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ½" Rod and Cap #30389 and replaced with a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" over Concrete Monument as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

26" Black Oak S52°W 35.32' Set spike and tag in Northwest side of 20" Red Pine S68°E 80.53' Set spike and tag in North side of tree. # 28" Black Oak N85°W 70.34' Set spike and tag in North side of tree.	6 #3
12" White Pine N60°E 72.84' Set spike and tag In North side of tree.	
Signed by Mannon & Ochs	Date <u>December</u> 20, 1996
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Approved by Peer Review Group On December 23. 1996

Norman L. Ochs, County Representative.

d May 14, 1975

Revised Jan., 1983

