SURVEY & REMONUMENTATION

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY
REGISTER OF DEEDS
LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code #		Linda	m. Brow
1. Public Land Survey	T <u>14N</u> R <u>12W</u> T <u>15N</u> R <u>12W</u> T R T R	F1 3	VOL. $oldsymbol{2}$	PAGE	9
 Property Controlling in Section Miscellaneous 	STR STR		102. 7	HUL	
Property in Sec.	STR		gister of Deeds S	stamp & File N	lumber
4. Lot No, Recor, Recor	in a field survey on October 1 rements of P. A. 74, Michigan P., above were in conformance with int manual of survey instructions to u of Land Management or by a this mentioned in lines 3, 4 and the Michigan Board of Land shed, re-established, manument	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in	A B C D 2		J K L M
Note: Not more than 4 c recorded on this c	corners, all in the same the ertificate.		11 -30 - 29 - 11 - 32 - 32 - 32	33 34	-26 -25 - -2538
	-chron 24. Montoe 10	vaygo County, Michigan ownship, Newaygo Coun ND ACCESSORIES AND/O	nty, Michigan R SUBSEQUEN	T RESTORA	TION:

G.L.O. John Hodgson 1838 12" Hemlock S21°E 20 Links (13.2')#1 12" Hemlock S15°W 14 Links (9.24')#2

Delos G. Anderson (County Surveyor)
Book A Page's 291 and 292 April 18-19-20, 1900
Set Gas Pipe 3 feet long 6" diameter for corner in place of old Government Corner

Robert A. Griffin R.L.S. #13584 August 10, 1973 Found ½" X 30" Pipe at intersection Telephone Pole S56°W 36.74' #8 3" Triple Apple N34°E 33.10' #9 Lyle S. Shepherd R.L.S. #503 November 17, 1940 Book 81C Page 5 Found ½" Pipe Fence Post Southwest 36.7' #3 W. Sign Post N05°E 22.55' #4

Ralph A. Smith R.L.S. #3421 Book 70 Page 149 January 17, 1956 Found 1/2" Gas Pipe 12" Maple S72°E 85.7' #5 16" Oak N66°E 75.4' #6 10" Maple N34°W 44.1' #7



Robert A. Griffin R.L.S. #13584

November 17, 1982 LCRC #557

Found ½" Gas Pipe from Griffin witnesses. Set 5" X 36" concrete monument with brass cap. Telephone Pole S56°W 36.73' #8

Telephone Pole N70°W 140,72' #10

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Robert A. Griffin's concrete monument in the centerline of gravel road going West and in centerline of road going East and in centerline of road going South and fence going North is 36 feet West and the condition of the recorded witnesses are: #1 thru #9 gone, #10 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted Robert A. Griffin's concrete monument and raised with a big spike as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Pole N70°W 140.83' Set nail with tag in Southwest side of pole. #10 10" Triple Maple N60°E 45.25' Set nail with tag in Northwest side of 1	
5" Cherry S51°E 144.80' Set nail with tag in Northeast side of tree.	166.
12" Red Pine S40°W/97.31' Set nail with tag in Southeast side of tree.	<u> </u>
Signed by Norman L. Ochs .	DateOctober 17, 1996
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Approved by Peer Review Group On October 24, 1996
Norman L. Ochs, County Representative.

Revised May 14, 1975 Revised Jan., 1983

11.80