MAR 1 9 1998

1997 Newaygo County Remonumentation Project

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'98 MAR 6 PM 12 37

For corners in Newaygo (County)	Located in:	Corner Code#	Lind	am. Bowe
Public Land Survey Property Controlling in Section	T_15N R_14W TR TR STR STR	F-3	vol. 2	116
3. Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File	Number
do hereby certify that under rec points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bur Law and/or that the corner p conformance with the rules of Decree of a Court of Law; esta recovered, found as expressed	, in a field survey on Novemb quirements of P. A. 74, Michigan P.A. 2 above were in conformance with remember of survey instructions of eau of Land Management or by a coints mentioned in lines 3, 4 and f the Michigan Board of Land blished, re-established, monumenta- below: corners, all in the same to	A. of 1970, the comer egulations and rules of the United States decree of a Court of 15 above were in Surveyors or by a ed, re-monumented,	5 6 - 18 - 17 - 16 - 15 - 1	1
South One Quarter Corner,	Section 4, Beaver Township, N	ewaygo County, Michigan.	$\begin{array}{c} 12 \\ 13 \end{array} + \begin{array}{c} 31 + 32 + 33 + 34 + 3 \\ 13 \end{array}$	5 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856 18" Beech N21°E 10 Links (6.60') #1 18" Beech S06°W 31 Links (20.46') #2

Newaygo County Road Commission Iron (Approx) 12" Pignut S36°W 35.9' #3 18" Maple N31°W 33.5' #4

George Blass R.L.S. #5489
Consumers Power Company Section Break
March 1968 Drawing No. S-F 17051
Set P.K. Nail from old witnesses.
22" Maple N34°E 115.70' #5
20" Maple N28°W 34.21' #4
Fence Post South 36.21' #6

William M. Jacques (County Surveyor)

March 10, 1903 Book 1 Register of Deeds
Found the Original Bearing Tree and Stake.

William Fries Jr. R.L.S. #30389
April 29, 1996 Recorded in Liber 363, Page 9839
LCRC #1310 Found P.K. Nail in old fence lines North and South.
Set a ½" Rod and cap
33" Maple N43°E 115.19' #5
5" Ash S06°E 60.44' #7
6" Ash S55°W 72.14' #8
31" Maple N31°W 33.58' #4

B. DESCRIPTION ION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" by 18" Rerod 6" below grade in the centerline of the East and West bituminous road and in line with fence going South and remnants of fence going North. The condition of the recorded witnesses are: #1 thru #3 gone, #4 and #5 Good Condition, #6 fallen, #7 and #8 Good Condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed $\frac{1}{2}$ by 18" Rerod and set a 4" diameter Harrison cast iron monument 20" long marked "County Survey" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

36" Maple N28°W 33.50' Found Nail and Tag #30389 in root, Set Spike and Brass washer in East side of tree 33.50' #4 40" Maple N50°E 114.97' Found Nail and Tag #30389 in root, Found Nail and Tag #5489 mostly overgrown, Set spike and brass washer in West side of tree 115.37' #5

6" Ash (blazed) S01°E 60.49' Found Nail and Tag #30389 in root, Set Spike and brass washer in West side of tree 60.62' #7 6" Ash (blazed) S49°W 72.14' Found Nail and Tag #30389 in root, Set spike and brass washer in Westerly side of tree

$(2.14^{\circ} \#8)$ $(0 $	
Signed by 10 man J. Ochs	Date November 11,1997
Norman L. Ochs	
Surveyor's Michigan License No. <u>22439</u>	Form approved by Michigan State Board of
Approved by Peer Review Group on November 11, 1997	

Approved by Peer Review Group on November 11, 1997

Norman L. Ochs, County Representative.

NORMAN d of anti-surveyers PLAS 8, 19 11 P. Revised Man, 19 5 P. Revised Jan, 19 5 P. 22439