SURVEY & REMONUMENTATION

MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 37

For corners in			00 1 11.11	O 111 22 C
Newaygo (County)	Located in:	Corner Code#	Link	ras M. Oraco
1. Public Land Survey	T <u>15N</u> R <u>14W</u> T R T R T R	<u>K-9</u>	VOL. $oldsymbol{2}$	126
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR		Paginton & D. J. av	
4. Lot No, Recor 5. Private Claims	ded Plat		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	File Number
points mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poir conformance with the rules of	, in a field survey on October 2 irements of P. A. 74, Michigan P.A. above were in conformance with regnit manual of survey instructions of u of Land Management or by a dents mentioned in lines 3, 4 and 5 the Michigan Board of Land Sished, re-established, monumented show.	of 1970, the corner pulations and rules the United States acree of a Court of 5 above were in	5 18 17 16 15	2 + 1 - 11 + 12 - 3 + 14 + 13 - 2 + 23 + 24 -
Note: Not more than 4 co recorded on this ce	orners, all in the same tow ertificate.	n and range, may be		26 + 25 -
Southwest Corner, Section 24	l, Beaver Township, Newaygo C	County, Michigan.	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	+ 35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1857 18" White Pine N591/2°E 18 Links (11.88')#1 16" White Pine N55°W 25 Links (16.5')#2 20" White Pine N27°E 41 Links (27.06')#3

Robert A. Griffin R.L.S. #13584 LCRC #615 1983 Found 11/4" Iron Pipe Set 5" X 36" concrete monument with brass cap 12" Jack Pine N46°E 48.48' #4 Power Pole N71°W 114,53' #6 South One Quarter Corner, Section 23 West 2616.40' #7 South One Quarter Corner, Section 24, S89°42'46"E 2606.94' #8 Pine Post 4" X 4" South 33.10' #9

Newaygo County Road Commission Sheet 11/4" Well Point 8" Jack Pine N30°E 48.2' #4 12" Maple S45°E 130.8' #5 Power Pole N55°W 114.6' #6

Newaygo Engineering and Survey Company August 23, 1996 Drawing Number 96216B Found Large Spike

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Large Spike on top of Robert A. Griffin's 5" X 5" X 36" concrete monument with brass plate. The centerline of the East and West bituminous road is 1 foot South and on line with fence going South. The old trail road going North is 9 feet East. The condition of the recorded witnesses are: #1 thru #3 gone, #4 dead, #5 and #6 good condition, #7 did not measure, #8 measured previously, #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted Large Spike and R.A.G. concrete monument as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

12" Jack Pine (dead) N46°E 48.48' Found cabin spike in Southeasterly side of tree. #4	
· · · · · · · · · · · · · · · · · · ·	
	1 5
2 Vack Pine 50/ VV 46.95' Found cabin snike in West side of troo	
2" Jack Pine N47°E 56.16' Set spike and tag in Southeasterly side of tree.	

12" Jack Pine S07°W 46.95' Found cabin spike in West side of tree.	LAND SURVEYOR
12 back Fine N4/16 56.16 Set spike and tag in Southeasterly side of trop	22439
Signed by Norman L. Ochs Date October 7 1997	22439
Norman L. Ochs Date October 7, 1997	1410
Company and 38 22 24	

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975

Approved by Peer Review Group on November 11, 1997 Norman L. Ochs, County Representative.

Revised Jan., 1983

NORMAN L. OCHS