SURVEY & REMONUMENTATION

1995 Newaygo County Remonumentation Project

APR 04 1996

COMMISSION

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

PAGE

205

OGESTY For corners in REGISTER OF DEEDS Newaygo Located in: Corner Code # (County) T <u>16N</u> R <u>11W</u> 1. Public Land Survey C-6 188 FEB 21 AM 9 44 Malline Toogas 2. Property Controlling in Section Miscellaneous

Register of Deeds Stamp & File Number 4. Lot No. _, Recorded Plat A B C D E E G H I I K I 5. Private Claims

I, <u>Norman L. Ochs</u>, in a field survey on <u>May 15</u>, 19 95 do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

2 _ 6_	5	- 4	-3	2	
3					
4 - 7-	B	g	 10	1,1	
5					
6 -18-	7	16	 15	14	13
7					
819	20	 21	22	-23	24
9	ļ <u>_</u>				
100	29-	28	27	56	25
11	_				
12 31-	32-	33	34	3 <u>5</u>	36
13					

E. 1/4 Comer of Section 18, Barton Twp., Newaygo Co., MI

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye 1856 12" Hemlock N23°W 20Lks (13.2")#1 10" Hemlock S42°E 31Lks (20.46')#2

Lyle S. Shepherd's Witness Book No. 1 Pg. 134 (1914 to 1950) 30" Pine Stp. S65°E 401/2' #3 30" Pine Stp. S31°W 881/2 #4

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1¼" pipe. The centerline of road is 5 ft West and I measured 2564,33 ft from the N.W. Cor. to the W. ¼ Cor. of Sec. 17 and measured 2567.73 ft from the W. ¼ Cor. to the S.W. Cor. of Sec. 17 and the condition of the recorded witnesses are: #1 thru #4 gone.

I recovered the old William Jacques (Co. Surveyor) C. 1/4 Cor. position of Sec. 18 and checked his 2 old witnesses for 1907 within less than 1 ft, using true ¼ line intersections. Therefore I feel this ¼ Cor. must be in proper location. (See Wm. Jacques record witness book Pg. 133)

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 11/4" pipe and set a 4" dia. Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

14"-12" Tw. Cherry West 22.20' Spike in North side of tree. 12" Cherry S75°E 56.15' Spike in North side of tree. 6" Cherry S50°E 47.91' Spike in Southwest side of tree 12" R. Pine N55°E 73,60' Spike in Southeast side of tree 10man w Signed by Date ___September 11, 1995 Norman L. Ochs Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975

Approved by Peer Review Group on <u>September 26, 1995</u> Norman L. Ochs, County Representative.

Revised Jan., 1983

