REMONUMENTATION

1996 Newaygo County Remonumentation Project

MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'97 FEB 12 PM 4 45

Linda M. Brown

For corners in		. (Kulensky.	M. Disa
Newaygo Located in:	Corner Code#			
· "				•
1. Public Land Survey T 16N R 11W	K-12			
TR TR		- VOL. 2	DACE	90
T R	11.1	10L. 🚑	PAGE	36
2. Property Controlling S T R				
in Section STR 3. Miscellaneous STB				
Proportion Co.				
	<u>Reg</u>	ister of Deeds S	tamp & File	Number
4. Lot No, Recorded Plat			DEFG	
5. Private Claims	····	2		``````
		3	1-1-1-	å <u></u> ∤ -
1, Norman L. Ochs , in a field survey on December 10	10 08	4	- - -	· -
		s	P- -!- -	10
therefore as required in the current manual of our averaged	lations and rules		- - -	╏╼╏╼┤╼┤╸
Department of the Interior, Bureau of Land Management or by a deci	e United States Tee of a Court of	7 - 18 - 1	17-1-10-1-	15
conformance with the rules of the Michigan Daniel 5	above were in			 - - - -
	Veyors or by a	0 - 19-1-2	021	2
recovered, found as expressed below:	io monamenteu,	<u> </u> - -	- <u>-</u> - -	╏╼╎╼╎╼╎╌
Note: Not more than 4 corners, all in the same tow	•	1 1 1 7	50	7
recorded on this certificate.	n and range, may be	<u>''</u> - -		-
	T.	12 -313	2	135
West One Quarter Corner, Section 36, Barton Township	n Newayan County Mak	l		<u> </u>
A DESCRIPTION OF STATE	e, remargo country, which	nyan	~	
A. DESCRIPTION OF ORIGINAL MONUMENT AND	ACCESSORIES AND/OF	SUBSEQUENT	F PESTODA	TION
G.L.O. Militon Nye Resurvey 1856 7" Beech S46°W 14 Links (9.24')#1 7" Beech N58°E 10 Links (6.60')#2 Measured 39.40 Chains (2600.4') from the Southwest Corner to (2610.96') from the West One Quarter Corner to the Northwest	the West One Quarter Corr	ner Section 36 and	measured 39	56 Chaine
Lyle S. Shepherd R.L.S. #503	Corner of Section 36			ine origing
Winess Book Number 1 Page 131 "X" on Bolder N87°E 24.4' #3		•		
B. DESCRIPTION OF CORNER EVIDENCE FOUND A REESTABLISHING CORNER:	ND/OR METHOD APPL	IED IN RESTOR	RING OR	
Found nothing. I prorated G.L.O. distance on West line of said s map and I measured 2627.55 feet from the Northwest Corner to from the West One Quarter Corner to the Southwest Corner of S	ection and held G.L.O. angle	e at West One Qua	ırter Corner p	er G.L.O.
from the West One Quarter Corner to the Southwest Corner of S	ection 36 and the condition	er of Section 36 an of the recorded wit	d measured 2 nesses are:#	2616.93 feet 1 thru #3
C. DESCRIPTION OF MONUMENT FOR CORNER AN LOCATING THE POSITION OF THE CORNER:	D ACCESSORIES ESTA	ABLISHED TO P	ERPETUA	ΓE ,
Set 4" diameter Harrison cast iron monument 36" long marked "C accepted as a careful and faithful reestablishment fo the original c	ounty Surveyor" as a substa	ntial marker for the	section come	er and is
18" Red Oak S09°W 12.12' Set spike and tag in East side of tree. 6" Red Oak S82°E 28.05' Set spike and tag in North side of tree. 6" Red Oak N30°E 11.47' Set spike and tag in North side of tree.				
No4 VV 33.12 Set spike and tag in Southe	erly side of tree.			
Signed by Johnson & Children		. 4000		
Norman L. Ochs Surveyor's Michigan License No22439				
	Form approved by Michigan	State Board of Land S	Surveyors, Jan 2	28, 1971
Approved by Peer Review Group On <u>December 23, 1996</u> Norman L. Ochs, County Representative.			Revised May 1	14, 1975
M (I M)	AT EL		Revised Ja	n., 1983
// 7	# (\$. "		

NORMAN L OCHS