

MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE

400 FFR 17 PM 3 42

	FILING REQUI	REMENT OF ACT 74, MICH.	P.A. 1970 00 1 ED +	in a To
For corners in SECTION Newaygo (County)	Located in:	Corner Code#	Linda	M. Brown
1. Public Land Survey	T <u>16N</u> R <u>14W</u> T R T R T R	<u>C-7</u>	VOL. 2	273
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp	& File_Number
4. Lot No, Recoi	rded Plat	······································	1 A B C D E F G 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	H I J K L M
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curron Department of the Interior, Burellaw and/or that the corner poconformance with the rules of	in a field survey on <u>December</u> December Dec	P.A. of 1970, the corner of the United States and ecree of a Court of the United States and Ecree of a Court of the United States and 5 above were in Surveyors or by a	5 6 - 18 - 17 - 16 - 7 8 - 19 - 20 - 21 - 9	-1 1 1 1
Note: Not more than 4 corners, all in the same town and rang recorded on this certificate.		town and range, may be	11 12 - 31 - 32 - 33	-1 1 1
Northeast Corner, Section 19	9, Troy Township, Newaygo	County, Michigan	13	
A. DESCRIPTION OF O	RIGINAL MONUMENT AN	ND ACCESSORIES AND/C	OR SUBSEQUENT RES	TORATION:
G.L.O. Thomas Whelpley 36" White Pine S22¾°E 3 6" Beech N26½°E 15 Linl 12" Hemlock N56½°W 25	37 Links (24.42')#1 ks (9.9')#2	and South road. Re	er 28, 1969 Found ½" 5 eplaced (in the exact loca nforced concrete post 3 t	ntion) the steel rod
Newaygo County Road C	commission Sheet	26" White Oak N32°F 104 22' #6		

1/2" Steel Rod 12" Elm S75°W 74.10' #4 24" Beech N40°E 47.9' #5

Robert L. Wetherell R.L.S. 24624 December 14, 1979 26" White Oak N32°E 104.22' #6 21" White Oak S53°W 144.42' #8 6" White Oak N36°W 43.09' #9

4" X 7' Treated Pine Post East 33.16' #7

21" White Oak S53°W 144.42' #8

6" Red Oak N36°W 43.09' #9

West One Quarter Corner, Section 17, is N00°22'40"W (computed Bearing - not true bearing) 2607.46' #10

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 5" square concrete monument with brass cap on line with fence going East. The centerline of the North and South dirt road is 2 feet ± West. The condition of the recorded witnesses are #1 thru #5 gone, #6 good condition, #7 gone, #8 and #9 good condition, #10 did not verify.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 5" square concrete monument with brass cap as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner. WHITE STATES

36" White Oak (blazed) N36°E 104.51' Found cabin spike in East side of tree. #6	3	SE OF WICHIGHT	4.
24" White Oak (blazed) S62°W 144.32' Found cabin spike in Westerly side of tree. #8	بالمحج	NORMAN	."/4
24" Red Oak (blazed) N37°W 43.09' Found cabin spike in Northeast side of tree. #9	₹ ×		*
6" X 6' Treated Post East 34.33' Found spike with tag #22439 in North side of post.	2 ×	L, UUIIS	*
Signed by Norman L. Ocho Date December 18, 1998	3	SURVEYOR	70%
Norman L. Ochs	1/4 5	22439	
Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Land S	3urv a y	2 St 191 -08-197 - 0	₹
Approved by Peer Review Group On December 22, 1998	Revi	Stan May 14A 1975	r
Name 1 Octor Octor December 1			

Norman L. Ochs, County Representative.