UBER 16874 PG 169

JAN 39700131:



Signed by

Surveyor's Michigan License No.

24598

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Filing Requirement of Act 74, Mich. P.A. 1970 \$ 7.00 HISCELLANEOUS RECORDING \$ 2.00 REHOMMENTATION For corners in 3 JAN 97 7:53 A.M. RECEIPT# 8B RECORDED - DAKLAND COUNTY PAID Corner Code # Located In: Oakland LYNN D. ALLEN, CLERK/REGISTER OF DEEDS (county) T1N R8E 1. Public Land Survey Compliance with ACT 345, P.A. 1990 APPROVED ON: 12- 9- 96 OAKLAND COUNTY REMONUMENCAL 2. Property Controlling S PEER GROUP COMMITTEES in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. 4. Lot No. _____, Recorded Plat_ 5. Private Claims , in a field survey on November 26, 1996 Joseph C. Kapelzcak do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of 7 Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, & re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Set post in 1816 G.L.O. Survey. N 1 1/2° W. 10 lks 10" Beech. S. 7 1/2° E. 30 lks 10" Beech. There are no L.C.R.C.'s recorded at this time. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: SURVEY & Recovered 1/2" iron rod. REMONUMENTATION **Recovered Witnesses:** FILE N 05° W. 26,05' PK nail E. side 4" twin Elm. MAY 2 2 1997 N 05° E. 114.60' PK nail in W. side 6" Cottonwood. COMMISSION C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set concrete monument with Oakland County Remonumentation Brass Cap. Witnesses Set: ROFESSIONAL North 95.74' nail w/remon tag E. side 24" Ash. N 05° W. 26.05' nail w/remon tag in E. side 4" twin Elms. S 80° E. 79.37' nail w/remon tag in S.W. side twin 6" Box Elders. S 55° E. 114.60' nail w/remon tag in W. side 6" Cottonwood.

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983