LIBER 16874PG168

JAN 397001314

JAN 39700T314

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in								LANEO		EÇDRI	DING		
Oakland	Located In:	Corner Code #		J J PAI		77 :		A.H. ECORI				88 # COV	
(county)							EN,	CLER	K/RE	GIST			
Public Land Survey		B-11		\$ 4				MENTA ce wit					
•	T R T R ;				Α	CT 3	45. P	.A. 1	990	رب			
2. Property Controlling S	T R		APPR OAKI	OVE	D ()	N:	12 Y R	- Y-	96	FNEA) 316	 N	
in Section S	TR			Pl	EER	GRO	HUP (COM	1117	ħΕ			
3. Miscellaneous S Property in Sec. S	T R		Regist	er oi	De	eas	Sta	mp e	x 1-116	e Nu	mue	:r 	
4. Lot No, Record	ded Plat			A-	В	С	D	E f	G	H (ı i	к	L
5. Private Claims				2		Ì			$\overline{\mathbf{I}}$		_ [Ţ_
		7.5-1		3	Ĭ.	\perp		1	_	Ĭ.	<u></u>	_	
I. <u>Joseph C. Kapelzcak</u> do hereby certify that under requ	irements of P.A. 74	4, Michigan P.A. of 1970	, the corner points		- }-	+	8—	 	_	-10	_	+	-12-
mentioned in lines I and 2 above required in the current manual of su					+	╁	\vdash			-	\dashv	+	十
Bureau of Land Management or by a decree of a Court of Law and/or that the corner points							17—	16		1/5	1—14 	1	-13-
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,							20_	2 1		22-	23		_24-
re-monumented, recovered, found	as expressed belo	w:		9	+	+	+	$\vdash \vdash$	- -	+	-		+
NOTE: Not more than 4 corners, all in the same town and range, may be				10	-3¦0-	+	2 ⁹ 9	28- 	+	27-	—2¦6	+	-25-
recorded on this certi	ificate.			12	<u></u>	1	<u></u>		1	3.	7		丁
A. Description of original monu	ment and access	ories and/or subsequer	nt restoration:	13			<u></u>						Ľ
Set post 1816 G.L.O. Survey	y. N 03°E 5lks, 1	2" Tamerac, S 50°E 32	lks, 6" Maple										
B. Description of corner eviden	ice found and/or n	nethod applied in resto	ring or reestablish	ing	cor	ner:							
Recovered 5/8"rerod in 5/8"	pipe		4										
Recovered Witnesses:					a team	# St.							
S 61°W 40.60' nail in west side 14" Maple			SURVEY & REMONUMENTATION										
 S 48°W 39.18' PK nail w/tag 	in northwest side					, 40					,		
S 67°E 43.37' PK nail w/tag in north side 18" Maple N 13°W 29.06' PK nail w/tag in east side 18" dead Maple			MAY	2	2 1	997				FIL	Ľ		
N 48°E 35.05' PK nail w/tag N 73°W 55.85' nail in north s	in southeast side	20" dead Maple	COI	MM	IIS	SIC	M	~	1 20 20	J			
C. Description of monument for	corner and acce	ssories established to	perpetuate locatin	g th	e po	sitic	on o	f the	corr	ner:			
Set Oakland County Remon	umentation Brass	Cap on existing 5/8" re	eród	_	-			MANA	ba.				
Witnesses Set:				1		-	-	C'AY (C	7/2				
S 48°W 39.35' PK nail w/ rer S 67°E 43.43' PK nail w/rem N 13°W 29.10' PK nail w/ren N 20° E 67.98' PK nail w/ren	nonumentation wa monumentation wa	sher in north side 18" N asher in west side 18" N	/laple /laple		K/PR	OFE SUR	LC: ME YO 10.	ZAR DIMAS	2				
Signed by Just C.	Kapelezak	Da	ate 12/16	190	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	A S	999						
Surveyor's Michigan License N	/ / //	FOF	RM APPROVED BY MICHIGA	AN STA	ATE B	OARD	OF LA	ND SU	REV	ORS, JA ISED M EVISED	AY 14	1975	