

COPY

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Oakland</u> (county)	Located In:	Corner Code #
1. Public Land Survey	T <u>1N</u> R <u>8E</u>	<u>E-12</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

\$ 7.00 MISCELLANEOUS RECORDING
 \$ 2.00 REMONUMENTATION
 3 JAN 97 7:56 A.M. RECEIPT# 88
 PAID RECORDED - OAKLAND COUNTY
 LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with
 ACT 345, P.A. 1990
 APPROVED ON: 7-31-96 TMS
 OAKLAND COUNTY REMONUMENTATION
 PEER GROUP COMMITTEE
 Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Joseph C. Kapelczak in a field survey on 23 January, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	16	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Post set in 1816 G.L.O. survey: N 39 E 5lks, 10" Red Oak; N 84 W 3lks, 6" Lynn.
 LCRC L6028 P637
 Fouty, 1973, 1" square bolt
 Southeast 22.31' Set nail & flag 12" stump
 Southwest 34.03' Set nail & flag north side 16" Elm
 West 34.92' Set nail & flag north side fence post

**SURVEY &
 REMONUMENTATION**

MAY 22 1997

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered 1/2" rerod w/cap #24598 in monument box on centerline Beck Rd.
 Recovered witnesses: S 70 E 61.20' PK nail south side power pole
 Recovered evidence: N 84 W 60.07' 1/2" rerod southeast corner parcel #22-32-200-014
 N 84 W 33.58' Corner 4' wire fence, northeast corner parcel #22-32-400-023
 S 84 E 60.07' 1" pipe in concrete monument corner of Barclay Estates sub.

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set O.C. remonumentation brass cap on exsting 1/2" rerod.
 N 33 E 64.89' Tip of arrow on fire hydant
 N 84 E 61.03' PK/remon tag north side 8" Ash
 S 70 E 61.21' PK/remon tag south side power pole
 N 21 W 113.56' PK/remon tag east side 14" Willow



7.00
 2.00
 file

Signed by Joseph C. Kapelczak Date 7/12/96
 Surveyor's Michigan License No. 24598