UBER 16850N 421



LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				. n	84	utnem	(43PP	aua n	~~~~ <i></i>	7144			
Oakland	Located In:	Comer Code #		\$ 2.	.00	MISCEL RENON	IMENT	ATION	!				
· (county)			6	19 I FAII		6 11:(M. Ded -			# 17		
1. Public Land Survey	TR	<u>G-2</u>	3		(D.	ALLEN	CLE	RK/RE				-	
	T R—					345, F.	, ,				•		
2. Property Controlling Sin Section S	- <u> </u> K		OTTAN AJIAO	9715 130 C	ori:_ iotii	. 61	- 1 -	96	''3'/ T;	int!			
3. Miscellatieous 5 1 K						OUFC				.,,,,			
Property in Sec. S	_ T R		Registe	er of	Dec	ds Sta	amp	& File	Nur	nbei	r		
				-						_			
4. Lot No, Rec	orded Plat	······································		A	9	C D	E	FG	H I	J	ĸ	L	
5. Private Claims				2		<u> </u>			ŢŢ	_ <u>_</u> .		Ţ	
I, Joseph C, Kapelczak	. in a field sur	vev on 29 January . 19	996	3	+-	╄			+	_	+	+	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were in conformance with regulations and rules therefore as required					-}-	-		-	-10	17-	+	-{2	
in the current manual of survey in	were in conformance ynstructions of the Unite	with regulations and rules ther ed Slates Department of the Ir	retore as required nterior, Bureau of	6 -		++	+-		╂╌╂	-+	+	+	
Land Management or by a decre	ee of a Court of Law a	and/or that the corner points n	nentioned in lines	8	-19	17	+-1	8	-15	-14	+	-13	
3, 4 and 5 above were in confor a Decree of a Court of Law; est					+	╅╅	+	 	++	\dashv	+	+	
found as expressed below:	·	, , , , , , , , , , , , , , , , , , ,		8	-1 9 -	20-	- 2	!	-5,5	23	_	-24 	
NOTE: Not more than 4	corners, all in th	e same town and rang	e may be	9	+	 	+-		1		+	†	
recorded on this ce				10	-30 1	 2 9-	+-2	•	-27	26	+	-25 	
A Description of criminal way				12	1						7	力	
A. Description of original mo	nument and access	ones and/or subsequent re	ootor attorn.	13	-31— 	32	1-3		34	35		-34 	
1/2" rerod. West 0.71' PK nail north N 20 E 91.55' PK nail ea East 128.69' electric inst	st side 48" Walnut	Walnut (. •										
B. Description of corner evid	ence found and/or r	method applied in restoring	g or reestablishi	ng c	ome	er:							
Recovered 1/2" rerod w/cap not legible in east side 12" Walnut					SUAVEY &								
No witnesses.						NTA	716	M.					
			83 2	* 2 ·=									
		•	WA	7 2	2	997							
		•	San Carried	COMMISSION									
										٥,	,u f	įυ	
C. Description of monument	for comer and acce	essories established to perp	petuate locating	the	pos	ition o	f the	corn	er:	1	o ó		
Set Remonumentation	Brass Cap.			j		OF	MIC	AL STATE	A.	•			
N 45 E 90.92' set nail S 30 E 60.76" set nail	w/remon tag southy	west side 8" Elm	1	*	γ.	OSE	PH	CA		i			
S 20 W 33.52' set nail N 0.72' set nail w/remo				LICENSK	PF	APEL HOFES SURVI No 245	EYOF D. 9 8						
Signed by leukh C	Kapelors	Date	10/1/46	· •	The same	TESS THE	104	a .					
Surveyor's Michigan License	No. 2459	0	APPROVED BY MICHIGA	N ST	TE BC	ARD OF	LAND S	REV	ISED M	AY 14,	1975		
								×	EVISED	47311.			