## LIBER 15528rc 788

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 \$ 7.00 MISCELLANEOUS RECORDING

		\$ 2.00 REMONU	ENTATION
For corners in		19 JUL 95 2:00	
Oakland Located In:	Corner Code #		CORDED - CAKLAND COUNTY
(county)	Comer Code #	LYNN D. ALLEN:	CLERK/REGISTER OF DEEDS
(		Comm	liance with
	M-11	ACT 34	5, P.A. 1990
<u> R</u>		APPROVED ON: 7	12.95 Tan
		OAKLAND COUNTY	REMONUMENTATION
2. Property Controlling STR	· · · · · · · · · · · · · · · · · · ·	PEER GROU	P COMMITTEE
in Section S T R			
3. Miscellaneous S T R			
Property in Sec. S T R		Register of Deeds S	tamp & File Number
4. Lot No, Recorded Plat		ABCD	EFGHIJKL
4. Lotte, Noodidad Flat		îiřř	
5. Private Claims		<del>─────</del> ²├─ <del>┋</del> ─┼─┊─	╂┈╃┈╂┈╬╼┾┈╬┈┼┈┆╴
		3	╂┈┞┈╂┈┼
I, <u>Joseph C. Kapelczak</u> , in a field do hereby certify that under requirements of P.A			<del></del> <del>┃</del> <del>┃</del> <del>┃</del> <del>┃</del> <del>┃</del> <del>┃</del> <del>┃</del> <del>┃</del> <del>┃</del> <del></del>
mentioned in lines I and 2 above were in conformance			<del>┇</del>
in the current manual of survey instructions of the	United Slates Department of the Inter	or, Bureau 6	<del> </del>
of Land Management or by a decree of a Court of	Law and/or that the corner points m	entioned in	
lines 3, 4 and 5 above were in conformance with the or by a Decree of a Court of Law; established,			
recovered, found as expressed below:	To obtain the first terms of the first		
	_		
NOTE: Not more than 4 corners, all in	the same town and range,		1-28-1-27-1-26-1-25
recorded on this certificate.	•	11	<del>                                     </del>
A. Description of original monument and acc	essories and/or subsequent resto	ration: 12 31 32	<del>  33   34   35   36</del>
	<b></b>	13	<del>┦┈┧┉┇┈┇┈┞┈┞┈┞┈</del> ╄
Post set in 1816 G.O.L. survey: N 53 1/2 W 2			
1.000.1.5074.0.000	7" Ironwood		v
LCRC L 5871 P 889			
Jones 1972 Found 1/2" pipe S 30 E 81,47' 17" Walnut			
S 36 W 36,95' 17" Walnut	•	P	
N 38 W 76.51' 22" Hickory			•
•			
B. Description of corner evidence found and	or method applied in restoring or	reestablishing corner:	
		n / 1.0.040.	<b>n</b> .,
Recovered 5/8" rerod in monument box on c	enterline Haggerty Rd. & 12./5's	outh of centerline 9 Mile	Ka.
Recovered witnesses:			
1,00010104 Millionoo.			_
S 55 E 59.66' Nail w/washer northeast side	guy pole		7.00
S 54 E 59.54' PK nail w/washer southwest			100
S 50 W 51.52' Chiseled cross on top of cur	ъ		
•			
O Describing of many months as a second and	iiki-k-di-		of the paragr
C. Description of monument for corner and a Set 5/8" rerod with O.C. Remonumentation be		late locating the position	Of the content
Oct 070 10104 Wal O.O. Nomonamon and	rass sup replacing 5.5 Torou	نو <u>ر</u>	OF MIC.
N 41 E 105.14' PK/remon tag southeast sic			ATTENTO
S 54 E 59 57' PK/remon tag southwest side	e guy pole	#	JOSEPH C
14 09 44 190.10 Proteinor tag normeast side power pole with an interest side power pole with an interest side power pole with a side of the side of th			
N 38 W 93.11' PK/remon tag northeast side	e power poie		PROFESSIONAL &
		1,5%	SURVEYOR # 5
			No. 24598
		8//20	SA CONTRACTOR OF THE PARTY OF T
A hard	1 1	Ting.	OFESSIONAL
Signed by Gas (A) / No La Va	Date /	120 100	Chambridge
Signed by Wallet	Date	1/88/75	
Surveyor's Michigan License No. 245798 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971			
			REVISED MAY 14, 1975 REVISED JAN., 1983