

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland (County)

Located In: Farmington Twp. Corner Code #

1. Public Land Survey T 1-N R 9-E C-7
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

SURVEY & REMONUMENTATION

MAR 21 2000

SECTION

\$ 7.00 MISCELLANEOUS RECORDING

\$ 2.00 REMONUMENTATION

2 JAN 98 9:01 A.M. RECEIPTS 12A

PAID CONFORMANCE WITH RECORD ACT OAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

APPROVED ON: 4-16-97

OAKLAND COUNTY REMONUMENTATION

PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, John N. Redash, in a field survey on March 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Grid table with columns A-M and rows 1-13. A dot is present at row 7, column C.

A. Description of original monument and accessories and/or subsequent restoration:

Table with 5 columns: Date, Description, Name, License No., Notes. Includes entries for 1817, 1973, and 1976.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1/2" iron in monument box currently occupies this corner. The following witness ties were used to recover and verify its position:

Table listing field measurements and witness ties between various corners (B-7 to C-7, C-7 to C-8, C-7 to D-7).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation P.S. #37281" on the existing 1/2" iron rod in monument box. Witnesses are as follows:

Table listing bearings and distances for witness lines, along with descriptions of monuments like P.K. nail and sanitary manhole.



The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by [Signature]

Date April 24, 1997

Surveyor's Michigan License No. 37281