LIRER 17932 PC 768

Filing Red	RNER RECORDATION CERTIF quirement of Act 74, Mich. P.A	
Oakland Located In: Farming	gton Twp. Corner Code #	\$ 7.00 HISCELLANEOUS RECORDING
1. Public Land Survey	C-9 SURVEY & REMONUMENTATION	2 JAN 98 9:01 A.N. RECEIPTE 12A PAID RECORDED - WAKLAND COUNTY LYNN D. ALLENS CREAMFREGISTER OF DEETS
2. Property Controlling STR in Section STR 3. Miscellaneous STR Property in Sec. STR	MAR 21 2000 SECTION	APPROVED ON: 4-28-97 [3 OAKLAND COUNTY REMONUMENTATION PEER GROUP CONTROLS Register of Deeds Stamp & File Number
	·	
4. Lot No, Recorded Plat		A B C D E F G H I J K L
5. Private Claims		2 6 5 4 3 2 1 1 3 3 4 3 4 4 3 4 4 4 3 4 4 4 4 4 4 4
I, John N. Redash, in a field survey on March 6 requirements of P.A. 74, Michigan P.A. of 1970, the corner of the incomposition of the United States Department of the Interior decree of a Court of Law and for that the corner points men conformance with the rules of the Michigan Board of Land Law; established, re-established, monumented, recovered, for NOTE: Not more than 2 comers, all in the same town and	points mentioned in lines 1 and 2 aborequired in the current manual of surver, Bureau of Land Management or by tioned in lines 3, 4 and 5 above were Surveyors or by a Decree of a Court und as expressed below:	der 5
on this certificate.	range, may be recorded	11
A. Description of original monument and accessories 1817 Set post corner 1973 1/2" Pipe in monument box 1973 Found monument box 1973 Found monument box 1974 Found 3/8" rod in monument box 1974 1/2" Iron in monument box 1974 1/2" Iron in monument box 1986 Found nail in monument box 1986 Found 1" form pin in monument box	and/or subsequent restoration: S. Carpenter n/a N. Jones #02934 W. Carlson #14759 W. Carlson #14759 R. Kostecke #12584 D. Pawlaczyk #17632 D. Pawlaczyk #17632 D. Sandomierski #24616 G. Ward #22445	G.L.O. notes L.C.R.C. L6061, P391, 392 Survey L6079, P596 L.C.R.C. L6079, P606 L6185, P268, L.C.R.C. L6266, P865, 866 L.C.R.C. Survey L6274, P529 L.C.R.C. L9448, P172 L.C.R.C. L9793, P768
B. Description of corner evidence found and/or meth	od applied in restoring or reestabli	shing corner:
A 1/2" iron in monument box currently occupies this corner. Field measurements were made between the following corne		1
C-8 to C-9 B-9 to C-9 2651.14 meas. 2657.00 meas. 2640.00 Rec. G.L.O. 2640.00 Rec. G.L.O. 2649.95 Rec. Tax maps	C-9 to D-9 2622.34 meas. 2617.40 Rec. G.L.O. 2623.48 Tax maps	C-9 to C-10 mess. 2652.08 mess. 2640.00 rec. G.L.O.
C. Description of monument for corner and access	ories established to perpetuate lo	cating the position of the corner:
I placed a 2" diameter brass cap stamped "Oakland County F follows:	Remonumentation PS#37281" on the	A CHICAN
N. 61° W., 59.16' P.K. nail and remon. washer S.W. N. 47° E., 75.48' P.K. nail and remon. washer N.W. S. 43° E., 77.56' P.K. nail and remon. washer S.W. S. 57° W., 136.41' P.K. nailand remon. washer E. fac	/. face U-pole /. face U-pole	* REDASH ** PROFESSIONAL SURVEYOR No.
The selected location is accepted by me and generally of the position of the original corner.	accepted by Professional Surveyo	37281 ors and best available evidence
Orginos by	idaek.	DateApril 24. 1997
Surveyor's Michigan License No. 37281	FORM APPROVED BY N	MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1: REVISED MAY 14,15
		REVISED JAN., 1 REVISED OCT., 1