

LIBER 17932 PG 781

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Oakland (County)

Located In: Farmington Twp. Corner Code #

1. Public Land Survey T 1-N R 9-E E-11
T R SURVEY & REMONUMENTATION
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R SECTION

Compliance with ACT 345, P.A. 1990
APPROVED ON: 4-28-97 FS
OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, John N. Redash, in a field survey on March 6, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

\$ 7.00 MISCELLANEOUS RECORDING
\$ 2.00 REMONUMENTATION
2, JAN 98 9:03 A.M. RECEIVED 12A L M
PAID 6 RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
Grid with a dot at 11-32

A. Description of original monument and accessories and/or subsequent restoration:

Table with 4 columns: Year, Description, Name, and Reference. Includes entries for 1817, 1941, 1972, 1973, 1977, 1983, and 1992.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1/2" iron rod in monument box currently occupies this corner. The following witness ties were used to recover and verify its position. The current measurements match ties from L.C.R.C. L6988, P274. Field measurements were made between the following corners:

Table with 4 columns: Corner Pair, Measurement, and Reference. Includes pairs like E-10 to E-11, D-11 to E-11, E-11 to F-11, and E-11 to E-12.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation PS#37281" on the existing 1/2" iron in monument box. Witnesses are as follows:

Table with 3 columns: Bearing/Distance, Description, and Reference. Includes bearings like N. 32° E., 73.75' and descriptions like P.K. nail and remon. washer N.W. face U-pole.

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by [Signature]
Surveyor's Michigan License No. 37281

Date April 24, 1997

