

LIBER 17932 PG 787

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

Located In: Farmington Twp. Corner Code #

COPY

1. Public Land Survey

T 1-N R 9-E F-13

2. Property Controlling in Section

S T R

3. Miscellaneous Property in Sec.

S T R

SURVEY & REMONUMENTATION

MAR 21 2000

Compliance with ACT 345, P.A. 1990

APPROVED ON 5-14-97 BY OAKLAND COUNTY REMONUMENTATION COMMITTEE \$ 2.00 PER REMONUMENTATION REGISTER OF DEEDS STAMP RECEIPT # 120 PAID RECORDED - OAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

JA-298000235

4. Lot No. , Recorded Plat

5. Private Claims SECTION

I, John N. Redash, in a field survey on March 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Grid table with columns A-M and rows 1-13. A dot is present at row 12, column G.

A. Description of original monument and accessories and/or subsequent restoration:

Table with 4 columns: Year, Description, Name, and Notes. Rows include 1816 Set post corner, 1949 Not described, 1986 Not described.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A concrete monument in a monument box currently occupies this corner. Current measurements match the tie to the north 1/4 corner of Section 4 (T-1-S., R-9-E. )(F-1) from 1949 L. Fall & Assoc, Unrecorded survey.

Table with 3 columns: Measurement, Description, and Notes. Rows include E-13 to F-13, F-13 to G-13, and F-13 to F-1 (T-1-S., R-9-E.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation PS#37281" on the existing concrete monument in monument box. Witnesses are as follows:

Table with 3 columns: Bearing/Distance, Description, and Notes. Rows include N. 40° E., S. 45° E., S. 45° W., and Due East.



The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by [Signature]

Date March 24, 1997

Surveyor's Michigan License No. 37281

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1981 REVISED MAY 14, 1977 REVISED JAN., 1981 REVISED OCT., 1981