. NAY 2 2 1997.

	يعنى ودين	· 结 图 版 结 * 产 < 企 6 2 2 2 4	LAND CORNER RECORDATION CE		MISCELLANEOU	e prenontue
For	corners in	MMISSIC	Filing Requirement of Act 74, Mich	i. P.A. 1970, 7.00 2.00   3   1		
	Oakland (Co	d ounty)	Located in: Farmington Corner Code # Township	18 DEC PAID	96 1:36 P.M. RECORDE	RECEIPT# 358 D - OAKLAND COUNTY
1.	Public Land Survey		T <u>IN</u> R <u>9E</u> <u>I-9</u>	ע אורן	Complianc	/REGISTER OF DEEDS e with
			TR	·	ACT 345, P.,	
2.	Property C	Controlling	T R S T R		ZED ON: 10- 2	3-96 TS MONUMENTATION
	in Section		S T R	1	PEER GROUP C	OMMITTEE
3.	Miscellane Property in		STR	Registe	er of Deeds Star	mp & File Number
	r roperty ii	i Qec.	STR			
4.	Lot No	, R	Recorded Plat			
5.	Private Cla	ims			A B C D E	F G H I J K
				2	-65	
				3	┞╌╫═╁┈┼═╁┈	<del></del>
l, _	Randy Ko	lehouse	_ , in a field survey on <u>September 2</u> 19 uirements of P.A. 74 Michigan P.A. of 1970, the comer point	96 , 4	7-1-8-1-	9-10-11
in lir	nes 1 and 2	! above were in	n conformance with regulations and rules therefore as reg	uired in the		<del>                                     </del>
curre Man	ent manual ( agement or	of survey instru by a decree of a	ctions of the United States Department of the interior, Burn a Court of Law and/or that the comer points mentioned in line	eau of Land	17-	161514
abov	re were in co	onformance with	n the rules of the Michigan Board of Land Surveyors or by a	Decree of a	19 20-	-21
Cour	rt of Law; essed below	established, r:	re-established, monumented, re-monumented, recovered	i, found as		
NOT			rners, all in the same town and range, may be recorde	edi	30 29	23 27 26 26
		is certificate.		11		┼┼
A.	Descript	ion of original	monument and accessories and/or subsequent resto	oration: 12	31 32	33 35 35
l- <b>9</b>	1017	\A/+ u l - u	01.0			
1-9	1817 1942	Wampler N/A	G.L.O. Supervisor's Plat of Westhill Woods L. 49 P. 56	Set Post N/A		
	1958	Cole	Cert Survey	Iron in Monum	ent Box	
	1987	Wilkerson	L.C.R.C. L. 10206 P. 762	Iron		
	1990	N/A	O.C.R.C. Alignment Plan	N/A		
В.	Descript	ion of corner	evidence found and/or method applied in restoring or	r reestablishing co	orner:	
1-9	shows in not the i running Section ( to I-10 a	ons 50.12' Nor ntersection of East and Wes Corner as being	762 appears to be filed in error as no witnesses shown th and 46.0' South which would lead one to believe that a North, South, East and West road. Found a 3/8" is the 4' West of the C/L of Orchard Lake Road running of 3.74' West of construction C/L of Orchard Lake Road. Dakland County Road Commission Alignment Plan (19842).	t this corner would ron in a monumer North and South. . This corner chec	be in an East- nt box in the C O.C.R.C. Alig ks very closely	West road only and /L of 10 Mile Road Inment Plan shows the distance shown
	Measure	South 2650.6	9' to i-8 (G.L.O. = 2640.0') 2' to I-10 (G.L.O. ≈ 2640.0') (O.C.R.C. = 2650.35') (Sup ' to J-9 (G.L.O. = 2617.6') (O.C.R.C. = 2631.51')	o. Plat Westhill Wo	ods = 2650.4')	
C.	Descript	ion of monum	ent for corner and accessories established to perpet	uate locating the	position of the	corner:
1-9		the 3/8" iron nonument box	with a 5/8" x 24" rebar with brass cap stamped "Oak	kland County Rem	nonumentation	P.S. #25854" in an
	Set PK N	lail & Tao Stan	nped "Oakland Co. Remonumentation P.S. #25854" in S	SW Side DF Pole N	N 38° W 82 54'	18,7
	Set PK N Set PK N	lail & Tag Stam Iail & Tag Stam	nped "Oakland Co. Remonumentation P.S. #25854" in N nped "Oakland Co. Remonumentation P.S. #25854" in N	NW Side DE Pole N NE Side Guy Pole :	N 56° E 90.21' S 65° E 158.17'	2
	Jerry	un a ray staff	nped "Oakland Co. Remonumentation P.S. #25854" In S	s side ddy role S	92 W 194.15	MICH OF MICH
	The selec	cted location is	accepted by the Contractor and is generally accepted by	ov professional	350	RANDY J.
			vailable evidence of the position of the original corner.	A branchouse	Ĩ	KOLEHOUSE
Sian	ed by	and	Jelepan Date	12/10/9	(Ca) **	LAND SURVEYOR No.
9"			ARTH TECH			25854
Surv	eyor's Mich	igan License N	Vo		7	NS.