	•	E Commence	
For corners in	LAND	CORNER PEOPLE	TIFICATE 25884
	- 4018	Requirement of Act 74, Mich. P.	A 1ddAFR 21028 page
Oakiand	Longitude		\$9.00 MISC RECORDING
(County)	Located In:	Corner Code #	
1. Public Land Survey			POID PERCEPTE SE A.M. RECEIPTE 6667
Cand Survey	T2N R 7	F	PAID RECORDED - OAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEEL
	TR	<u>F-11</u>	A STAN WEDTS SEK OF DEE
,	TR	SURVEY &	
2. Property Controlling	T_RF	IEMO <u>NUMENT</u> ATION	
iii oeciion	S	ENOTADIMENTATION	Compliance with
3. Miscellaneous	S TR	MAR OS	ACT 345, P.A. 1990
Property in Sec.	S	MAR 21 2000	APPROVED ON: 9-29-99 JK
	R		
4.1.451	,	SECTION	
4. Lot No, Record	ded Plat	011014	Register of Deeds Stamp & File Numb
o. Frivate Claims			
			ABCDD
			1 E F G H I J K
i, Grant J. Ward, R.L.S., in a field survey on October 14, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, NOTE:			2 5 5 4 3 1
			3
			4 - 7 - 8 - 8 - 8 - 8
			5
			6
an exhitesed below	v:	established, re-established monuments	7 16 15 14 1
NOTE: Not more than 2 comes		inconumented,	
on this certificate	s, all in the same town and re	inge, may be recorded	8 19 20 21 22 23
		o , may no recorded	
			10 30 29 28
			11 26 2
A. Description of original monument and accessories and/or subsequent restoration:			12-31-32-32
, and original monum	ent and accessories and/o	[Subsequent	13 34 35 3
F-11 Post, per G.L.O. No			
7 FS. G.Z.O. NO	ites.		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

North 1/4 corner of Section 33, T. 2 N., R. 7 E. Found 5/8" Bent fron Rod. Previously Unrecorded.

This corner location is accepted by the contractor and is generally accepted by professional surveyors es the best available evidence of the position of the original corner.

Section of more and accessories established to perpetuate locating the position of the corner.

F-11 Set 5/8" Iron Rod and Remonumentation Cap. GRANT 1 Set 60d Nail & Remonumentation Disc in East face WARD S 35° E LAND 25,711 Set 60d Nail & Remonumentation Disc in SURVEYOR Southwest face of 24" Cherry. NO. S 45° W 52.611 Set 60d Nail & Remonumentation Disc in North 22445 N 60° W 38.49' Set 60d Nail & Remonumentation Disc in LAND Southwest face of 8" Cherry. Signed by Surveyor's Michigan License No. 22445 July 12, 1999

SEPTEMBER 19, 1999

Corner Code: F-11

DOSSIER FOR: THE SOUTH 1/4 CORNER OF SECTION 28, MILFORD TOWNSHIP, T 2 N, R 7 E, OAKLAND COUNTY, MICHIGAN. Prepared under contract with the County of Oakland Under Act 345 of the Public Acts of 1990.

HISTORY:

This Corner has been accepted and used since before 1934 as witnessed by the Road Commission for Oakland County at that time. This Corner has not been previously recorded.

COLLATERAL EVIDENCE:

We found a bent 5/8" iron rod and set a 5/8" iron rod and and remonumentation cap in its place. This Corner lies 4 feet North of the Centerline of Maple Road (gravel). There are fence corners 33 feet North and 33 feet South of the Corner. We found a concrete monument 32.97 feet North of the Corner. We measured 1.62 feet less than the recorded distance to the Southwest Corner of Section 28 per the HCMA survey. We searched at least 50 feet in each direction for other stakes and found none that might represent the Corner.

SURVEYOR'S RECOMMENDATIONS:

This corner location is accepted by the Contractor and is generally accepted by Professional Surveyors as the best available evidence of the position of the original Corner. Therefore, I recommend that the Peer Review Group accept this Corner as monumented, with the references as shown on the enclosed form prepared according to Act 74 of the Public Acts of 1970.

Grant J. Ward, R.L.S. License No. 22445

SURVEY & REMONUMENTATION

MAR 21 2000

SECTION