DEC 26 96 30 96 20



Surveyor's Michigan License No. 33138

LIBER 16860 16091

COMMIS	5510N		ORNER RECOR				88		. (4500	*****		~ *!!#		
For corners in		riling K	equirement of a	ACT /4, WHEN. P	7.A. 1970 	\$ 2.	.00	NISCE REMON 6 9:	UNENT	TAT 10	W	DING CEIPT	# 7R	
Oakland	- 1. st	Located In:	Corner Code	e#		PAII)		RECOF	RDED	- OAK	LAND	COUNTY DEEDS	
(county)														
Public Land Sur	rvey	T 2N R 8E T R	C-7					Com ACT 3	•	n triffi A - 191				
		T R			AT	PROS		N:				TS	5	
Property Control in Section	olling S S	T R T R			OA	KLA	ND C	OUNT LGRO	1 86	MON	JA EN	TATE	021	
Miscellaneous Property in Sec	s . s	T R T R T R		7	Regis	ster c	f De	eds S	Stam	p & F	ile N	umbe	er	_
4. Lot No	, Record	ded Plat	-	·	·	•	в (. 0	e :		ш.	ı	K L	м
5. Private Claims						٦	ŢŢ	Ţ	֓֞֞֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֓֓֡֓֓֡֓֡֓֓֡֓֡	Ť	Ï	Ť		٦
_						3	6-	5				2_		
I,James E. Kova do hereby certify the	at under requ	irements of P.A. 7	74, Michigan P.A.	of 1970, the co			ļ	 	 - -	_	10	\1 1\1	12-	-
mentioned in lines I required in the currer	and 2 above	were in conformative instructions of	ance with regulati of the United States	ons and rules the Department of the	erefore as	5	╂╾╂	\dashv	╂╌╂	-	1-1	-	╂═┼╌	d
Bureau of Land Mar mentioned in lines 3	nagement or	by a decree of a	Court of Law an	d/or that the co	rner points	٦,	19	— 17— 	16		18	—14— ———	13-	1
Land Surveyors or I	by a Decree	of a Court of Law	v; established, re-			-1	19	—20—	21		22_	23	24]
re-monumented, rec	overed, found	as expressed belo	OW:			9	1		-	-	+-1	+	-	-
NOTE: Not more recorded	than 4 co		he same town	and range, n	nay be	10	30-	29 	25		27-	2 ⁶	25-	-
A. Description of o	riginal monu	ment and access	ories and/or sub	sequent restora	tion:	12	3 <mark>1</mark>	3 <mark>2</mark>	32		34	35 1	36	+
C-7				•		13			1				1	-J
1816 - G.L.O. Set 1954 - Ash Engine		ey, no monumen	t description, no	accessories, D	istance: B	-7 to	C-7	= 263	39.35	ō'.				
_			•											
					, '									
B. Description of	corner evid	ence found and	l/or method app	olied in restori	ng or rees	tabli	ishin	g co	rner	;				
C-7 No monument	t or accessor	ries found												
Distance: C-5 to C	:-8 = 7920.00	0' (G.L.O.); 7916.	.85' (Wade-Trim)										
C-7 was re-establis proportioning between	een G.L.O. c	orners (C-5 to C	-8).	-	-							.41	, FILE	
The resulting di	stances betw	een corners is a	is follows:	C-7 to B-7 = $\frac{2}{3}$ C-7 to F-7 = $\frac{7}{3}$								7,) i	
C. Description of	monument	for corner and a	accessories est	tablished to pe	rpetuate l	locat	ing t	the p	ositi	on o	f the	corr	er:	
C-7 Set Concrete	Monument w	rith Brass Oaklar	nd Co. Remon C	ap# 33138, in	Marsh			, ,						-
	-	ellow Carsonite F Set 60d Nail/ Oa	kland Remon Br	ass Tag# 3313				arack		ATE	OF I	VIC/	GAN	L.
\$50)°E 126.08' S	Set 60d Nail/ Oak	dand Remon Bra	nis witness tree ass Tag# 33138 nis witness tree	NE Face	4" El	m			1	JAM E KOV LAI	AS ND_	*	******
t									RECV		SURV No 331	o.	JANA S	-
Signed by	ans.	E. Kova	3	Date	Decem	ber 2	20, 1	996_	*	CPE	D L	AND	S	