# SURVEY & REMONUMENTATIO

### LIBER 17325 N 327

MAR 0 4 1998	
SECTION Located In:  LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 19  Troy Twp. Corner Code #	70 \$ 9.00 MISCELLANEOUS RECORDING \$ 2.00 REMONUMENTATION 24 JUN 97 3:37 P.M. RECEIPT* 179A
1. Public Land Survey  T_2N R_11E D-13  T R  T R	PAID RECORDED - GAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Compliance with ACT 345, P.A. 1990  APPROVED ON: 5 - 9 - 9 7 TS  OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE  Register of Deeds Stamp & File Number
4. Let No. Recorded Dist	
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKLM
	2 6 5 4 3 2 1
7	3
I, Huston K. Kennedy, in a field survey on 4/1, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	4 7 8 9 10 11 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 19 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	7 9 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9 20 21 22 23 24
on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration. 1817-GLO Wampler, D.S.; Set Post 7" Ironwood S26°W 13 Links; 16" Beech N36°E 15 Links 1.) 1988-Patterson, PS #17631; LCRC L.10484, Pg.889 - Fnd P.K. Nail	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  1997 Kennedy Surveying, Inc Kennedy, PS #17623 - The corner as recovered is in the intersection of 14 Wile Road 2 feet South of the existing centerline of the East bound lane extending to the East & West, which has a bituminous surface, and 1.20 feet West of the existing centerline of Leafdale extending to the North, which has a concrete surface. Also 41 feet West of the existing	
centerline of Leafdale extending to the South, which has a concrete surface.	
Witnesses from LCRC #1 were used to recover and verify the location of the set P.	
I accepted the set P.K. Nail as the best evidence of the original corner position	1. graph /
Field measurements between see back side of LCRC	4 J
C. Description of monument for corner and accessories established to perpetuate locating the pos	ition of the corner:
D-13 I replaced the set P.K. Nail with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #17623 in a new Monument Box N11°W 176.97' Set PK & Remon Washer NE face Power Pole	
N43°E 63.26' Set PK & Remon Washer SE face Power Pole N66°W 133.72' SE corner of building #2500	OF MONOTON
SO5°W 77.57' NE corner of house #2503	HILLIAN HUSTON
East 133.04 Ft. North 1/4 corner of Section 5, TiN, RilE, Royal Oak Twp., (D-1)	HUSTON KENNEDY
The selected location is accepted by me and is generally accepted by Professional Sur	45 25 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
position of the original corner.	17623
Signed by Date S	5-8-97 PARECCIONAL SURFEREN
Surveyor's Michigan License No. 17623	WANTE COOKSINE TO AND

## SURVEY & REMONUMENTATION

MAR 0 4 1998

UBER 17325 N 328

**SECTION** 

#### FIELD MEASUREMENTS BETWEEN

#### D-13 to C-13

GLO = 40 chains or 2640.00 Ft. No sidwell or plat distances are available GPS-MEA = 2623.43

#### D-13 to D-1

No GLO GPS-MEA = 133.04

#### D-13 to E-13

GLO = 40 chains or 2640.00 Ft. "CUMMINGSTON PARK" + "CUMMINGSTON PARK NO. 1" = 2657.94 Ft. GPS-MEA = 2657.70