SURVEY & REMONUMENTATION

UBER 17156 PG 248

MAR 04 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74 Mich PA 1970

| Filing Requirement of Act 74, Mich. P.A. 1 | 970 | | | | | |
|--|------------------------------|---------------------------------|--|-------------------------|---|--|
| SECTION | | | | | | |
| Oakland Located In: Troy Twp. Corner Code # | | \$ 9.00 MISCELLANEOUS RECORDING | | | | |
| (County) | \$ 2.00 | REMONUNE | | ~~~ ~~~ | P' () | |
| 1. Public Land Survey T 2N R 11E K-11 | 24 HYK PAID | 97 8:45 (| i.n. | ECEIPT# | | |
| <u>TR</u> | | | ERK/REGIST | | | |
| TR | | Compli | idčė,., | - | | |
| 2. Property Controlling S T R | | | P.A. 1990 | 10 | | |
| in Section S T R | APPROVE | D ON: 4- | 16-97 | 13 | | |
| 3. Miscellaneous S T R Property in Sec. S T R | | ER GROUI ER GROUI | REMONUTE COMMIT | . > 3 \ 1 ' | | |
| 1. (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c | Regis | ter of Deed | s Stamp & | File Nu | mber | |
| | | | | | | |
| 4. Lot No, Recorded Plat | A B | CDE | F G H | IJĸ | стм | |
| 5. Private Claims | 1 | ĬĬĬ | ÌΪΪ | | וווו | |
| | 2 6 | 5 | 4-1-3- | <u> </u> | <u> </u> | |
| Hucton K Konnedy in a fall amount 3/17 co 97 | 3 | | | | | |
| I, <u>Huston K. Kennedy</u> , in a field survey on <u>3/17</u> , 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in | 4 - 7 - | <u> </u> | 9 | 11 | 12 | |
| conformance with regulations and rules therefore as required in the current manual of survey instructions of the | 5 | 1-1-1- | 1 | | | |
| United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan | 6 -18 | 17 | 15— | 14- | -1,3- | |
| Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented | 7 | | | | | |
| recovered, found as expressed below: | 8 -19- | 20 | 2122 | 23 | 24 | |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded | 9 | | | | | |
| on this certificate. | 10 30- | 29 | 27 | 26 | 25— | |
| | 11 | | | | | |
| | 12 31- | 323 | 34 | 35 | 36 | |
| 1817-GLO Wampler, D.S.; Set Post 6" Beech N73°E 14 Links; 14" Sugar S70°W 4 Links 1.) 1978-Parish, PS #24609; LCRC L.7129, Pg.758 - Fnd Handhole 2.) 1987-Buckerfield, PS #10868; LCRC L.9803, Pg.552 - Fnd P.K. Nail 3.) 1989-Donnelly, PS #21563; LCRC L.11062, Pg.22 - Set P.K. Nail 4.) 1991-Penn, PS #23505; LCRC L.11732, Pg.444 - Fnd P.K. Nail 5.) 1962-McDaniel Unrecorded Survey - Object found not stated, no witnesses 6.) 1991-City of Troy witnesses - Fnd P.K. Nail | | | | | | |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing cor 1997 Kennedy Surveying, Inc Kennedy, PS #17623 - Fnd P.K. Nail in the center of the West, which has a bituminous surface and John R. Road extending to the North & S Witnesses from LCRC # 3, 4 and the City of Troy unrecorded witnesses were used to | he intersect South, which | has a bit | uminous su | rface. | | |
| P.K. Nail. | . 1000101 0. | nu volili | uic 100uci | /II V1 CI | ic round | |
| I accepted the found P.K. Nail as the best evidence of the original corner posit | tion. | | ζ\ ^{lé} | | | |
| Field measurements between see back side of LCRC | | | 90° 20° 20° 20° 20° 20° 20° 20° 20° 20° 2 | / | | |
| C. Description of monument for corner and accessories established to perpetuate locating the po | sition of the | corner: | • | | | |
| K-11 I replaced the found P.K. Nail with a 5/8" x 24" Iron Rod w/2" diameter brass ca #17623 in a new Monument Box N46°E 71.24' Set PK & Remon Washer SE face Power Pole S50°E 100.61' Set PK & Remon Washer SW face Power Pole | ap stamped (| Oakland Cou | inty Remonu | mentat <u>i</u> | on, PS | |
| S50°W 80.36' Center of NW bolt in concrete base for Light Pole N55°W 79.89' Set PK & Remon Washer NE face Light Pole | | | S OF M | CHICAS | | |
| The selected location is accepted by me and is generally accepted by Professional Su position of the original corner. | - | | OROPEOSIO | vidence NAL | the | |
| Signed by Date 4 | -17-5 | 海氢人 | SURVEYO 17023 | R | ines, | |
| Surveyor's Michigan License No. 17623 | | 20 | PANERON | Chile | N. S. | |
| | | "Het. | NOFESSION | ingertain. | | |

SURVEY & REMONUMENTATION

MAR 0 4 1998

SECTION

LIBER 17156 N 249

FIELD MEASUREMENTS BETWEEN

<u>K-11 to J-11</u>

GLO = 39.56 chains or 2610.96 Ft.
"JOHN R. GARDEN" + "SUPERVISOR'S PLAT NO. 21" + "SUPERVISOR'S PLAT NO. 30" = 2592.85 Ft.
"CAMBRIDGE HEIGHTS" + SUPERVISOR'S PLAT NO. 29" + Parcels = 2591.50 Ft.
GPS-MEA = 2592.97 Ft.

K-11 to K-10

GLO = 40 chains or 2640.00 Ft.
"JOHN R. GARDEN" = 2440.34 Ft.
"SUSSEX PARK" + "SUPERVISOR'S PLAT OF MAPLE ACRES" = 2440.34 Ft.
GPS-MEA = 2439.40 Ft.

K-11 to K-12

GLO = 40 chains or 2640.00 Ft.
M.C.S. = 2831.26 Ft. (No date stated)
"RIND INDUSTRAIL PARK" + Parcels = 2832.73 Ft.
GPS-MEA = 2833.20 Ft.

K-11 to L-11

GLO = 39.70 chains or 2620.20 Ft.
"SUPERVISOR'S PLAT OF MAPLE ACRES" = 2643.58 Ft.
"GULASON SUBDIVISION" + FAIRGROVE SUBDIVISION" + Parcels = 2644.26 Ft.
GPS-MEA = 2644.16 Ft.