unn 19872 prog1

For corners in	LAND CORNER RECORDATION CERTIL Filing Requirement of Act 74, Mich. P.A.	FICATE 139679
Onleton		LIBER 19872 PAGE 91
	cated In: Corner Code #	\$7.00 MISC RECORDING \$2.00 RENDMUNENTATION
(County) Hig	hland Township	04/22/1999 07:54:23 A.K. RECEIPT# 22152
1. Public Land Survey	•	t PAID KECURDED - UAKLAND COUNTY
The done Land Survey	<u>T3N R7E D-1</u>	G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS
	TR	
1	T R	1
2. Property Controlling S	L_ R_ SUBMEY &	
in Section	- T R	Compliance with
3. Miscellaneous	T R	ACT 345, P./t., 1990
Property in Sec. S		APPROVED ON: 4-15-99 JS
Ŭ	- 1 - K	OAKLAND COUNTY REMONUNCESTATION
	}	LERK CROCK CASIMITAL E
Lot No, Recorded Plat Private Claims,	SECTION	Register of Deeds Stamp & File Number
5. Private Claims		·
		ABCBEFGHIJKLM
i i		
. 11		3 3 1 2 1 3 1 2 1 3 1 3 1 3 1 3 1 3 1 3
Huston K. Kennedy , in a field	survey on March 1, 1999 do hereby state that under 0, the corner points mentioned in lines 1 and 3 at that	³ ┞ ╏╏╏ ┼┼┼┼┼┼┼┼
conformance with regulations and rules the	survey on March 1, 1999 do hereby state that under 0, the corner points mentioned in lines 1 and 2 above were in re as required in the current manual of surveys.	4 7 9 9 10 11 12
United States Department of the Interior, Burea	to the corner points mentioned in lines 1 and 2 above were in the sar required in the current manual of survey instructions of the u of Land Management or by a decree of a Court of Law and/or d 5 above were in conformance with the adventor	5
Board of Land Surveyors of the Co. 3, 4 and	u of Land Management or by a decree of a Court of Law and/or d Sabove were in conformence with the rules of the Michigan a Court of Law; established, we established	6-18-17-16
recovered, found as expressed below:	d 5 above were in conformance with the rules of the Michigan a Court of Law; established, re-established, monumented,	7
	,	8 19 70
NOTE: Not more than 2 corners of in the		22-1-23-1-24
NOTE: Not more than 2 corners, all in the on this certificate.	e same town and range, may be recorded	9
		10 30 29 28 27 26 25
		11
		12-31-32-33
A. Description of original		34-35-36-
1815, 1936OLO	d accessories and/or subsequent restoration	130-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
A. Description of original monument and accessories and/or subsequent restoration: 1815- 1826GLO Holmes, D.S.; No post was set, no witnesses		
B. Description of corner widows a		
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: 1999-Kennedy Surveying, Inc. — Kennedy, PS #17623 - The corner was not set during the original government survey but has found capped ½" Iron Rod and the large rock with all the large rock with the large r		
seen perpendent in him makes at the control of the		
found capped 1/2" Iron Rod and the large rock within large rock within all the distance but has		
the best evidence of the comment is raige took with chiseled "+" is \$15°F 1 22 feet 1 accorded to		
T4N, R7E, Rose Township (D-13) is located 324.21 feet to the East. The corner was reset on the township line and is located rock w/chiseled "+" as in a old fence, tree and rock row extending to the East & West. I found no evidence to dispute the location of the found is located rock w/chiseled "+".		
in a old fence, tree and rock row extending to the East & West. I found no evidence to dispute the location of the found large		
rock w/chiseled "+".	to the Last & West. I found no evidence	ce to dispute the location of the found large
FIELD MEASURMENTS BETWEEN		
D-1 to C-1	D-1 to E-1 No GLO No sidwell or plat distances 2715.83 Ft. (GPS-MEA) d accessories established to perpetuate locating the poseled d"+" with a 4" diameter Concrete Monument Remonumentation, PS #17623 on the trwn line	
No GLO	D-1 to E-1	
No sidwell or plat distances	No GLO	WHITE OF MICHAEL
2709.09 Ft. (GPS-MEA)	No sidwell or plat distances	Mark Commence of Carling
D.4 to D.42	27 15.83 Ft. (GPS-MEA)	HUSTON
No GLO		KENNEDY 4
324,21 Ft (GPS-MEA)		PROFESSIONAL & E
(S. S. MEA)		SURVEYOR
0 B		11023
C. Description of monument for corner an	d accessories established to manuscus.	POSTOCOUNT SHE
bross are replaced the large rock w/chis	eled d"+" with a 4" diameter Consult locating the po	osition of the corner: 1000 COSTUTATION
Due Wood 19 and County	Remonumentation PS #17822 and the form	with ½" Iron Rod 36" long w/2" diameter
N08°E 27.70' Set Mag Nail & Remon Washer South face 26" Oak S24°E 18.35' Set Mag Nail & Remon Washer West face 17" Cherry S30°W 34.25' Set Mag Nail & Remon Washer NE face 13" Maple		
S30°W 34 25' Sat Mag Nail & Remo	n Washer NE face 13" Manle	10
S30°W 34.25' Set Mag Nail & Remo East 324.21', South 1/2 corner Section	m Washer SE face 20" Oak	/
A SOUNDI DECHIC	31 32, 14N, R7E, Rose Township (D-13)	\mathcal{K} ,
The selected location is accounted to	and to	
The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of		
	January Cur	To as the pest available evidence of
Signed by:		
Surveyor's Michignan License No. 176	72 Date 4-	-10-79
/ Live was regulated Liberse No. //	623	