

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OAKLAND COUNTY
T 3N R 8E

DESCRIPTION OF CORNER 1/8 POST IN THE CENTER OF NE 1/4 OF SEC. 27

CORNER MONUMENT MON. BOX IN E OXBOW LAKE ROAD

DATE MONUMENT ~~RECORDED~~ WITNESSED APRIL 1971

WITNESSES TO CORNER..... N 53°W 61.80' POWER POLE



N 83°E 77.45' 12" OAK

N 32°E 60.45' NORTH END OF 24" CONK. CONVEYOR

AND

N 20°W 80.4' SOUTH END 12" CONK. CONVEYOR

CIRCLE CORNER REGISTERED

26' SOUTH OF CENTERLINE OF MILL RD. AS EXISTING

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SURVEYOR'S SEAL

SIGNED _____ DATE _____

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68