LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| | · | | 2 |
|---|---|---|---|
| FOR CORNERS OF -: | LOCATED IN -: | CORNER CODE NUMBER | Jula See 2. Q |
| 1. PUBLIC LAND SURVEY | T. 3 N. R. 8 E. | 2-I | 11/4 |
| 2. PROPERTY CONTROLL- ING IN SECTION——— | | | 2 DELANGE |
| 3. MISCELLANEOUS PROPERTY IN SECTION | , T N E V E W. | | () h. |
| 4. LOT NO , REC | | | |
| 5. PRIVATE CLAIMS | | | REGISTER OF DEEDS STAMP AND FILING NUMBER |
| do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on April 13 1922, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: | | | |
| A. Description of original monument and accessories and/or subsequent restoration: | | | |
| DETROIT EDISON COMPANY. | | | |
| B. Description of corner evide | ence found and/or method a | pplied in restoring or re-estab | lishing corner: |
| | | | |
| N52°E 3 N 26°E 3 S 66°W 5 S 09 W 6 N 64°E | 51.0' IROM I 64.4' POWER 91.4' POWER 28.3' 5" 0. | PIDE POLE POLE AC DEEN -13" (EDAR | ating the position of the corner: |
| SIGNED BY | | DATE | |
| SURVEYOR'S MICHIGAN RE | GISTRATION NO. | | (SEAL) |
| FOR STATE AND UNITED ST | | | |
| SIGNED BY | CHIEF OF SURVEY PARTY | DATE | |
| APPROVED AND SIGNED BY | MICHIGAN REGISTERED I | LAND SURVEYOR DATE | (SEAL) |